Introduction

Fluor Daniel, Inc. (FDI) was tasked by the Environmental Protection Agency (EPA) Region 6 to conduct Site Inspection Prioritization (SIP) activities at the Olin - Wallisville Rd. site, in Houston, Harris County, Texas (EPA ID No. TXD000607028). A phased approach was implemented for each site under this Work Assignment (WA). A preliminary site score was developed utilizing the PA-Score computer program. The PA-Score was completed using historical data provided by EPA Region 6. Additional data was then collected and a PREscore packaged was completed. This report summarizes the information which has been reviewed and collected for Olin - Wallisville Road Site.

Site Description/Background Information

The Olin - Wallisville Road site (also known as the S.P. Oliver site) is an 18-acre lot located at 7621 Wallisville Road in Houston, Harris county, Texas. It is bordered on the north and west by residential lots, on the east by the Houston Belt and Terminal railway line, and on the south by Wallisville road (Figure 1) (2,001). The geographic coordinates of the site are 29°17′20" West longitude.

From 1938 to 1950, the Southern Acid and Sulfur Company owned and operated a sulfur plant at the location. the facility was purchased in 1950 by Olin Corporation ("Olin") for dry formulation of pesticides; liquid formulation of pesticides was added in 1955. during operations at the Olin Facility, two fire ponds and a disposal pit were located in the northern dumps, piles, and widespread areas of fugitive dust generation and deposition, many of which were covered during later construction activities. Prior to the installation of drainage tiles underneath the site in 1971, portions of the site would frequently remain under water for days during periods of high precipitation (4,009). The site drainage ditches lead to Hunting Bayou and then the houston Ship Channel, which is the major surface water drainage course for the area (6,002).

In 1972, the property was sold to Eureka Investment Company which demolished the facility, covered the entire site with 6-8 inches of soil, subdivided the lot and resold sections as follows: Southern Pacific Railroad acquired 9 acres comprising the eastern portion of the site, bordering the Houston Belt right-of-way. Southern Pacific Railroad covered their portion of the original Olin site with three feet of stabilized limestone and used the site for container storage. The remaining 9 acres were acquired by Mustang Industrial Equipment Company (owned by Eureka Investment Company) (3,002). Mustang in turn leased the northern 3 1/2 acres of their portion to Seatrain Service Inc. (6,001). Seatrain also stabilized their acreage with limestone and used it as a parking area for transport containers. Mustang Industrial Equipment was built on the southwest portion of the site.

In December, 1980, a preliminary survey of the area by EPA Region 6 revealed four toxaphene-containing piles approximately 18 inches high and 3-4 feet in diameter, on the north end of the railway right-of-way. In January 1981 the Houston Belt and Terminal

Fluor Daniel, Inc.

Railway Company "Houston Belt" contracted Rollins Environmental to remove these materials, which were then transferred to seven 55-gallon drums and removed to a licensed disposal facility (7,Attachment A1,005).

During February, 1981, EPA, Region 6, conducted a subsequent sampling and analysis effort. In addition to the Houston Belt right-of-way, EPA also sampled properties occupied by Southern Pacific, Mustang and Seatrain, and several adjacent off-site locations. Three pesticides; toxaphene, DDT, and pentachloronitrobenzene (PCNB) were detected. Pesticide contamination also was found in the drainways bordering the north and east boundaries of the property (7, Attachment A1, 006).

A surface removal action conducted by Olin in compliance with an Attorney General's Order in 1988 removed 3 to 4 feet of affected soils from a drainage area to the north of the site: as well as from the railway right-of-way and site areas adjacent to the railway. Excavated areas were then re-filled with clean fill (8, 001). Currently, Texas Natural Resources Conservation Commission (TNRCC) is actively monitoring the site. The latest sampling inspection by TNRCC was conducted in June 1995.

Waste Characteristics/Waste Quantity

Weston presented a summary and short profile on the various compounds of potential concern at the S.P. Oliver site within their 1985 Site Assessment Report (3, 006-013). The contaminants of concern at the site (Compounds present at 10s to 100s of ppm) were: Lindane, Pentachloronitrobenzene, 4,4'-DDT, 4,4'-DDD, 4,4'-DDE; Toxaphene was detected within site soils at levels over 1,000 ppm (mg/kg) (12, 001). The waste material from the other section of the site was removed during the surface removal ordered by the Attorney General (8, 001).

Ground Water Migration Pathway

The site is located in the Beaumont geological formation, which is characterized by alternating layers of clay, silt, and sand derived from stream channel, point bar, natural levee and backswamp deposits. Thickness ranges from 100 feet with thinning to the northwest and thickening to the south. the Beaumont formation lies stratigraphically above the Montgomery Formation (also composed of alternating clays, silts and sand and approximately 100 + feet in the investigation area); the two units are hydraulically connected by basal sands and are the two upper units of the Chicot Aquifer (5, Attachment 1, 002).

The depth to ground water at the site is approximately 20 feet (4, 008). Annual precipitation for the region is 49.17 inches (25, 001); annual net precipitation at this location is 4.68 inches per year (26, 001).

There are numerous ground water wells within 1 4-mile radius of the site; however, as the site exists within an urban/industrial sector of the City of Houston, there are few domestic use wells within the first 3 miles of the site. There are no confirmed users of water derived

from wells within sectors lying within 1 1/2 to 1 mile radius of the site, 1 to 2 miles of the site, or 2 to 3 miles of the site. The majority of individuals utilizing ground water within this region obtain their water from either the City of Houston (3 wells located at slightly over 3 miles west/northwest of the site) or Jacinto City (3 wells also located at slightly over 3 miles east/southeast of the site).

Jacinto City is a town of approximately 10,000 people which obtains approximately 20% of its drinking water from its own wells with 80% supplied through surface water obtained from the City of Houston (16, 001). Based on these values, approximately 2,000 people from Jacinto City utilize ground water obtained from the three wells located within 3 to 4 miles of the site.

The City of Houston Municipal Water Supply supplies approximately 1.7 million people with water obtained from both ground water and surface water sources. the population served by ground water in Houston is approximately 738,836 (21, 001). The number of persons on average served by each of the wells within 4 miles of the site (three wells within the City of Houston "Northeast" well cluster) is 6,232. The total number of persons estimated to be served by the three Northeast wells is 18,695 (21 001).

There are approximately 20,695 people supplied with drinking water derived from ground water obtained from areas 3 to 4 miles from the site (City of Houston and Jacinto City wells).

Surface Water Migration Pathway

The site drainage ditches enters into Hunting Bayou located approximately 1/3 mile from the site. Hunting Bayou flows for approximately 11 miles and enters into the Houston Ship channel (6, 002), (3, 003). The remainder of the 15-mile target distance limit (TDL) is within the Houston Ship Channel.

Although Hunting Bayou and the Houston ship Channel are perennial water bodies, recreational uses are at a minimum. Commercial fishing does not occur on these waters (13, 001). there are no drinking water intakes within the 15 mile TDL (14, 001); (10, 001); (10, 001).

Soil Exposure Pathway

The site is fenced and located in an industrialized area within the City of Houston. Residential housing is present on the north and west borders of the Olin site; previous investigations of these areas have shown site contaminants to be present within the soils of some of these residential lots (8, 001); (9, 001-005).

Based on GEMs population database (23, 002) and confirmed with topographical information (5, 001 - 004), there are no on-site residents, but 174 residents live within 1/4 mile of the site. There are no residents located between 1/4 and 1/2 mile of the site. The population within the 1/2 to 1 mile sector is 7588. There are no terrestrial or sensitive, environment,

schools or daycare centers located within 200 feet of an area of the site. The site and the area around the site have no obvious recreational attractiveness.

Air Migration Pathway

The Texas Natural Heritage Program (THNP) was contacted to evaluate the potential existence of endangered species within a 4-mile radius of the site (22, 001). TNHP personnel listed three species which could conceivably use this area as habitat, although the likelihood of finding these species was described as "very unlikely". the species were: Prairie Dawn, flowering annual, Texas Windmill Grass, grass species, Houston Machaeranthera, grass species.

Wetlands acreage totals approximately 180 acres 4 miles of the site (24, 001-004). Based on GEMS population database, the resident population is 25,074 between 1 to 2 miles from the site, 38,483 from 2 to 3 miles, and 85,146 from 3 to 4 miles totaling 156,465 for a 4 mile radius.

No air release has been observed, and although some site-related compounds may be exposed at surface either on site, on adjacent lots or within drainways leading off site, the volatilities of the site contaminants are extremely low (7, Attachment A1,004).

Summary

The Olin-Wallisville Road site (also known as the S.P. Oliver site) is an 18-acre lot located at 7621 Wallisville Road, Houston, Texas. The site is currently unused and sparsely vegetated, with some areas paved or overlain by concrete pads. From 1938 to 1950, the Southern Acid and Sulfur Company owned and operated a sulfur plant at the location. The facility was purchased in 1950 by Olin Corporation for the formulation of dry and liquid pesticides, which continued until the early 1970s.

Early sampling and analysis efforts by EPA at the site and adjacent locations revealed the presence of pesticides; toxaphene, DDT and PCNB. Pesticide contamination also was found in the drainways bordering the north and east boundaries of the property (7, Attachment A1, 006). Site oversight responsibilities were acquired by the Texas Natural Resources conservation Commission (TNRCC; at that time TDWR) in July, 1984. Since that time, TNRCC has conducted water, soil and air sampling at or near the site.

Olin conducted a surface removal at the site in 1988. Affected soils were removed from the eastern perimeter of the site (adjacent to the rail line) as well as along the site's northern boundary (which borders residential lots). This surface removal was conducted in compliance with an Attorney General's Order (8, 001).

Six municipal water supply wells are located within a 4-mile radius of the site. However, these wells are located between the 3 to 4 mile radius of the site. The surface water near the site is used for industrial release. Site contaminants have a very low solubility and volatility.

References

- 1. Record of Communication To: Steve Hamm, TNRCC, Houston District Office, From: Ken Jensen, Fluor Daniel, Inc., Regarding Current Agency (TNRCC) Activities at the S.P. Oliver Site, 05/17/95.
- 2. Record of Communication To: Bob Devillier, City of Houston Zoning and Planning Department From: Ken Jensen, Fluor Daniel, Inc., Regarding Zoning of the S.P. Oliver site 05/16/95.
- 3. U.S. Environmental Protection Agency, 1980. Potential Hazardous Waste Site Inspection Report. Author Bill Carrothers, 12/29/80. (Included in EPA file)
- 4. Herschfield, David M., 1961, U.S. Department of Commerce U.S. Weather Bureau. Technical Paper Number 40 Rainfall Frequency Atlas of the United States.
- 5. U.S. Environmental Protection Agency, Graphical Exposure Modeling System (GEMS) Database, compiled from the U.S. Census Bureau 1990 data, accessed 03/27/95.
- 6. U.S. Environmental Protection Agency, 1985. Hazard Ranking System scoring document, 10/10/85. (Included in EPA file)
- 7. Texas Water Development Board, Records of Wells, Springs, and Test Holes for Harris County, 1995. (Included in EPA file)
- 8. Record of Communication To: Rudy Hodge, Water Engineer, City of Houston From: Ken Jensen, Fluor Daniel, Inc., Regarding City of Houston Water Supply, 05/30/95.
- 9. U.S. Environmental Protection Agency. Final Rule Hazard Ranking System, FR51532-51667, December 14, 1990.
- Record of Communication To: Tom Parker, Harris County Flood Control District, -From: Ken Jensen, Fluor Daniel, Inc. - Regarding Surface Water Usage in Areas Adjacent and Downstream of the S.P. Oliver Site, 06/02/95.
- 11. Record of Communication To: Dave Terry, Texas Natural Resources Conservation Commission From: Ken Jensen, Fluor Daniel, Inc. Regarding Wellhead Protection Areas in vicinity of S.P. Oliver site.
- 12. Record Of Communication To: Johnnie Kennedy, TNRCC, Houston District Office From: Ken Jensen, Fluor Daniel, Inc. Regarding Current Agency (TNRCC) Activities at the S.P. Oliver Site, 05/17/95.

- 13. Ecology and Environment, Inc., February 10, 1982. Memorandum From: Imre Sekelyhidi, Environmental Engineer, E&E, Region VI To: Dave Peters, Chief, Hazardous Wastes Section. (Included in EPA file)
- 14. Roy F. Weston, Inc., 1985, Site Assessment Report on S.P. Oliver Pesticide Plant, Houston, Harris County, Texas, 10/21/85. (Included in EPA file)
- 15. Facsimile Transmission From: Tom Michel, Data Processing Manager, Harris-Galveston Coastal Subsidence District To: Ken Jensen, Fluor Daniel, Inc. Regarding Registered Wells Located Within a 4-Mile Radius of the Site, 05/19/95.
- Record of Communication To: Mark Leudke, Lance Robinson, TNRRCC Fisheries Personnel Covering Galveston Bay - From: Ken Jensen, Fluor Daniel, Inc. - Regarding recreational and Commercial Fishing Within Hunting Bayou and The Houston Ship Channel, 05/15/95.
- Stennie Meadours, TNRCC, 1990. Memo To: Ernest Heyer, Head, Program Services Unit, Field Operations Division, TNRCC (Texas Water Commission). Subject: "Olin/Texas Water Commission Settlement Agreement; Sample Analysis Results", 05/17/90.
- 18. Record Of Communication To: Shannon Breslin, Texas Natural Heritage Program Resource Protection Division From: Ken Jensen, Fluor Daniel, Inc., Regarding Endangered Species Within the TDL of the S.P. Oliver Site, 05/23/95.
- 19. U.S. Department of the Interior, Fish and Wildlife Service, National Wetlands Inventory Maps: Stettegast, TX, Jacinto City, TX, Park Place, TX, Pasadena, TX.
- 20. U. S. Geological Survey, 7.5-minute topographic maps: Settegast (1982), Jacinto City (1982), Park Place (1982) and Pasadena (1983), Texas.
- 21. Texas Water Resources Data, Water Year 1991, Volume 2. San Jacinto River Basin, Brazos River Basin, San Bernard River Basin, and Intervening Coastal Basins. U.S. Geological Survey Report TX-91-2.
- 22. U.S. Department of Commerce County and City Data Book, 1994.
- 23. Land Resources Laboratory Map Series: Land and Water Resources Houston-Galveston Area Council. Bureau of Economic Geology, 1975.
- 24. U.S. Geological Survey, Water Resources Investigations Report 87-4153. Ground-Water Withdrawals and Changes in Ground-Water Levels, Ground-Water Quality, Etc. in the Houston District, Texas, 1980-84.

- 25. Geologic Atlas of Texas, Houston Sheet, 1:250,000. Bureau of Economic Geology, Austin, Texas, 1982.
- 26. U.S. Environmental Protection Agency. Hazard Ranking System Guidance Manual. EPA540-R-92-026. November 1992.
- 27. Record of Communication To: John Cooper, Jacinto City Water Department From: Ken Jensen, Fluor Daniel, Inc. Regarding Jacinto City Water Supply, 05/22/95.

FIGURE 1 SITE LOCATION MAP






FIGURE 1
SITE LOCATION MAP
Olin-Wallisville Road (S.P. Oliver) Site
EPA ID No. TXD000607028
Houston, Harris County, Texas

Record of Communication To: Steve Hamm, TNRCC, Houston District Office From: Ken Jensen, Fluor Daniel, Inc., Regarding Current Agency (TNRCC) Activities at the S.P. Oliver Site, 5/17/95.

Date:

17 May 95 2:45 pm PST

Time:

From:

Steve Hamm

Entity/Position:

Site Project Manager - TNRCC

Phone #:

(713) 625-7305

To:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

Relevant Information:

Steve called back with additional information in response to questions we had discussed earlier in the day:

- Although a surface removal action was planned as far back as 1985, no action was taken at the site until late 1988 or early 1989. TNRCC was providing oversight on the site at this time and had been doing so since the early 80s. TNRCC does not have in its posession reports to indicate exactly on what dates the removal actions at the site took place, nor are there any reports confirming the effectiveness of the removal action in terms of decreasing significantly the levels of contaminants remaining on site. An August 1989 report of samples derived from site soils/sediments showed 10s to 100s of ppm (mg/kg) of pesticides remaining on site soils following the surface removal activities. Because of this, additional sampling was ordered (executed early in 1995); the laboratory analysis of these samples has not been performed as of 17 May 1995.
- 2) Documentation in the posession of TNRCC does not specify which firm or entity oversaw the removal action; documents only state that "Olin" was the party executing the removal action. Woodward Clyde was named in one document as a party to "provide recommendations" on the excavation, but it is not clear whether they were at the site representing the PRPs or the TNRCC. TNRCC documents indicate Olin was planning to remove soils in some areas to 3 ft depth and in other more highly contaminated areas down to 4 ft. All areas were then backfilled with clean fill.
- 3) The ditch which is indicated within older documents as running down the center of the site is still in existence, although this area was subjected to soils removal and backfilling in the 1988/1989 surface removal action. Excluding the area occupied by Mustang equipment, the site consists of vegetated soils and pads of structural concrete. The site is fenced. Salina St. borders the site to the north.

Record of Communication to: Bob Devillier, City of Houston Zoning and Planning Department, From: Ken Jensen, Fluor Daniel, Inc., Regarding Zoning of the S.P. Oliver site 5/16/95.

Date:

16 May 95

Time:

2:05 pm PST

Call

From:

Ken Jensen

Entity/Position:

: F

Phone #:

Fluor Daniel (714) 975-2106

To:

Bob Devillier

Entity/Position:

City of Houston - Zoning and Planning Dept

Phone #:

(713) 754-9616

Relevant Information:

Bob provided the following information on the site located at 7621 Wallisville Rd., Harris Co.:

On FEMA maps the site is zoned "X", appears on panel 245G (map date 9/28/90).

U.S. Environmental Protection Agency, 1980. Potential Hazardous Waste Site Inspection Report. Author Bill Carrothers, 12/29/80. (Included in EPA File)

SEPA

POT L HAZARDOUS WASTE SITE STIE INSPECTION REPORT

GION SITE NUMBER (to be exalgned by Hg)

TX1538

GENERAL INSTRUCTIONS: Complete Sections I and III through XV of this form as completely as possible. Then use the information on this form to develop a Tentative Disposition (Section II). File this form in its entirety in the regional Hazardous Waste Log File. Be sure to include all appropriate Supplemental Reports in the file. Submit a copy of the forms to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Tack Force (EN-335); 401 M St., SW; Washington, DC 20460.

tection Agency; Site Tracking System; Hazardous Weste Enforcement Tack Force (EN-335); 401 M St., SW; Washington, DC 20460.									
I. SITE IDENTIFICATION									
A. SITE NAME S.P. OLIVER YARD (SO. PACIFIC B. STREET (or other identifier)									
	NDUSTRIAL EQUIPMENT 7600								
• •	Olin-Houston Chemical Co	• / •	F. COUNTY NAME						
HOUSTON G. SITE OPERATOR INFORMATION		77020	Harris						
1. NAME S.P. Oliver Yard	: Mr. Dan Novasad, Yard Ma	anager ,	(7/3) 113-659/ 2. TELEPHONE NUMBER						
Mustang Industrial: Mr	. Chuck Chalker, Prop. Mar	nager	(713) 460-2000						
3. STREET Southern Pacifi	c Trans. 4. CITY P.O. Box	15640	S. STATE 6. ZIP CODE						
Co., Wallisville & Loc		13040	TX 177020						
									
I. NAME S.P. Oliver Yard			2. TELEPHONE NUMBER						
Mustang: Eureka Invest	ment Co.								
3. CITY	/C	, ,	4. STATE B. ZIP CODE						
C/O Mr. Unuck Unalker,	(Same address & telephone	e number)							
and operated by the Ol	re site formerly occupied	by a pesticide to	ormulating plant owned						
J. TYPE OF OWNERSHIP	in Corporation.	TO COLLAR CORE							
1. FEDERAL 2. STAT	E 3. COUNTY 4. MUNI	CIPAL X 5. PRIVAT	·E						
	2 0 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3		7 mi + 1						
	II. TENTATIVE DISPOSITION (com	olete this section lest)							
A. ESTIMATE DATE OF TENTATIVE	B. APPARENT SERIOUSNESS OF PR								
DISPOSITION (mo., day, & yr.)	1. HIGH 2. MED	IUM 💢 3. LOW	. T A. NONE						
C. PREPARER INFORMATION									
1. NAME BILL Carrothe	2. TEI	LEPHONE NUMBER	3. DATE (mo., day, & yr.)						
Bill Carrothers		742-4522	12/29/80						
A. PRINCIPAL INSPECTOR INFORMA	III. INSPECTION INFO	RMATION							
1. NAME	2. TIT	LE							
Mr. Bill Carrothers	FIT	Chemist							
3. ORGANIZATION			4. TELEPHONE NO. (area code & no.)						
Ecology and Environmen	t. Inc.		(214) 742-4522						
B. INSPECTION PARTICIPANTS			<u> </u>						
I. NAME	2. ORGANIZATIO	ON	3. TELEPHONE NO.						
	Ecology and Environment,	Inc							
Mr. H.K. Ray	1509 Main, Dallas, TX	75201	(214) 742-4522						
Mr. Clarence Johnson	TDWQ, Deer Park, TX		(713) 479-5981						
;									
	/IEWED (corporate officiale, workers, real	deada)							
	2. TITLE & TELEPHONE NO.		ADDRESS						
1. NAME	Z. III CE & I E CEPHONE NO.		ADURESS						
David S. Harcus	Fourinment Dienstehen		. 0001						
David 3. Haicus	Equipment Dispatcher Seatrain Pacific Services	Salina Stree							
David 3. Harcus	Seatrain Pacific Services	s Houston TX	77020						
	Seatrain Pacific Service Finance Manager	s Houston TX 7607 Wa	77020 Ilisville Rd.						
Mr. Ben Torrance	Seatrain Pacific Services	s Houston TX 7607 Wa	77020						
	Seatrain Pacific Service Finance Manager Mustang Industrial Equip	s Houston. TX 7607 Wa ment Co. Houston	77020 						
Mr. Ben Torrance	Seatrain Pacific Service Finance Manager Mustang Industrial Equip Property Manager Mustang Industrial Equip Chemical Engineer	Ment Co. Houston To Houston The Houston The Houston To Houston To Houston To Houston	77020 						
Mr. Ben Torrance	Seatrain Pacific Service Finance Manager Mustang Industrial Equip Property Manager Mustang Industrial Equip	s Houston. TX 7607 Wa ment Co. Houston	77020 						
Mr. Ben Torrance Mr. Chuck Chalker	Seatrain Pacific Service Finance Manager Mustang Industrial Equip Property Manager Mustang Industrial Equip Chemical Engineer	Ment Co. Houston To Houston The Houston The Houston To Houston To Houston To Houston	77020 						
Mr. Ben Torrance Mr. Chuck Chalker	Seatrain Pacific Service Finance Manager Mustang Industrial Equip Property Manager Mustang Industrial Equip Chemical Engineer	Ment Co. Houston To Houston The Houston The Houston To Houston To Houston To Houston							

Herschfield, David M., 1961, U.S. Department of Commerce - U.S. Weather Bureau. Technical Paper Number 40 - Rainfall Frequency Atlas of the United States.

WEATHER BUREAU F. W. REIGHERDERFER, Chief

TECHNICAL PAPER NO. 40

RAINFALL FREQUENCY ATLAS OF THE UNITED STATES

for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years


Prepared by DAVID M. HERSEFIELD

Cooperative Studies Section, Hydrologic Services Division

for

Engineering Division, Soil Conservation Service U.S. Department of Agriculture





04-002

U.S. Environmental Protection Agency, Graphical Exposure Modeling System (GEMS) Database, compiled from the U.S. Census Bureau 1990 data, accessed 3/27/95.

COVERAGE

=======

STATE COUNTY STATE NAME

COUNTY NAME

201 48 Texas Harris Co

CENTER POINT AT STATE : 48 Texas

COUNTY: 201 Harris Co

REGION OF THE COUNTRY

Zipcode found: 77020 at a distance of 3.9 Km

STATE	CITY NAME	COMMUNITY	FIPSCODE	LATITUDE	LONGITUDE
тx	HOUSTON	DENVER HARBOR	48201	29.7767	95.3283

CENSUS DATA

z===========

Olin (Corp.
--------	-------

LATITUDE 29:47:26		:47:26 LC	ONGITUDE	95:17:27	1990 F	OPULATION	
	. بإ		1.9	p 2,	3	, 4,	
	4						SECTOR
KM	0.00400	.400800	.800-1.60	1.60-3.20	3.20-4.80	4.80-6.40	TOTALS
S 1	0	0	0	4841	6460	20525	31826
S 2	0	0	108	1657	1524	14901	18190
S 3	. 0	0	2500	7178	7900	24272	41850
S 4	174	. 0	4980	11398	22599	25448	64599
RING	3 174	0	7588	25074	38483	85146	156465
TOT	ALS						

STAR STATION

=========

WBAN				PERIOD OF-	DISTANCE
NUMBER	STATION NAME	LATITUDE	LONGITUDE	RECORD	(km)
12918	HOUSTON/HOBBY TX	29.6500	95.2833	1964-1968	15.6
12960	HOUSTON/INTCONT TX	29.9833	95.3667	1981-1985	22.6
12906	HOUSTON/ELLINGTON TX	29.6167	95.1667	1966-1970	22.7
12923	GALVESTON/SCHOLES TX	29.2667	94.8667	1956-1960	71.2
12917	PRT ARTHUR/JEFFERSON CO TX	29.9500	94.0167	1981-1985	124.0
93987	LUFKIN/ANGELINA CO TX	31.2333	94.7500	1967-1971	168.4
12912	VICTORIA/FOSTER TX	28.8500	96.9167	1965-1974	189.0

U.S. SOIL DATA

STATE : TEXAS

LATITUDE : 29:47:26 LONGITUDE : 95:17:27

THE STATION IS INSIDE H.U. 12040104

GROUND WATER ZONE : 10

RUNOFF SOIL TYPE : 1

EROSION : 1.1210E-03 CM/MONTH

DEPTH TO GROUND WATER BETWEEN : 3.0000E+03 AND 3.0000E+03

FIELD CAPACITY FOR TOP SOIL : 6.0000E-02

EFFECTIVE POROSITY BETWEEN : 2.0000E-02 AND 3.0000E-01

SEEPAGE TO GROUNDWATER BETWEEN: 4.6330E+03 AND 1.3900E+04 CM/MONTH

DISTANCE TO DRINKING WELL : 2.8000E+04 CM

U.S. Environmental Protection Agency, 1985. Hazard Ranking System Scoring document, 10/10/85 (Included in EPA File).

Texas Water Development Board, Records of Wells, Springs, and Test Holes for Harris County, 1995 (Included in EPA File).

TEXAS WATER DEVELOPMENT BOARD GROUND WATER DATA SYSTEM

RECORDS OF WELLS, SPRINGS, AND TEST HOLES
COUNTY - Harris

Site # 112 Wells 7, 7, 10, 11, 22, 31, 36 are within 4-mi radius of SP Oliver Site. Only 9, 10, 11 are currently used

.1	٠,	,	. .	2		COOM	ı - naii	15		1	, (-)	<u>''</u>		
2	ply) Hei		OWNER	LAT.	LONG.	SOURCE OF COORDS.	WATER BEARING UNIT	DEPTH OF WELL (FT.)	DATE COM PLETED	WELL TYPE		WATER LEVEL AVAIL.	QUAL.
۔ عمر	55 1	15	101	Tidwell Timbers MUD Verde Forest	295101	951406		121EVGL	1272	1971	w	P	M	Y
6	55 1	15	103	(b) (6)					214	1969	W		N	N
ć	55 1	15	106	Greenwood Utility	295116	951310		121EVGL	1195	1970	W	P	M	Y
ć	55 1	15	204	Royat Wood MUD	295115	951115	5	121EVGL	812	1962	W	P	М	Y
ć	55 '	15	210	Jackstone Subdivision	295030	951039		112CHCT	397	1980	W	P	M [.]	N
6	55 '	15	211	Parkway U.D.	295109	951207		121EVGL	1022	1982	W	P	M:	N
6	55 '	15	212	Houston Cheers Industrial Center	295038	951120		112CHCT	595	1981	W	P	M	N;
ć	55 '	15	301	Harris County FWSD 48	295115	950845	. 5	112CEVG	786	1960	W	P	М	Y
ć	55 ·	15	304	Southland Paper Mill	295229	950741		121EVGL	1608	1966	u	N	С	Y
•	55 °	15	306	Arco Chem. Co.	295004	950735	1		1561	09 1975	u		N	N:
6	55	15	308	Evans Cooperage	295205	950800		112CHCT	532	1980	W	N	M	N
(65 ·	15	309	Richmond Stimwell	295218	950837		112CHCT	635	1982	W	Р	М	N
(65 ·	15	311	NORTH STAR STEEL	295035	950801	1	112GLFC	365	1988	w	N		
•	65	15	400	٠	294958	951336	J.1	112GLFC	125	1900	W	ĭ ~		
6	65	15	401	Houston Lighting and Power Co.,Greens Bayou	294919	951311	$F^{\gamma^{\alpha}}$	121EVGL	1489	1947	w	N	н .	N
(55 ·	15	402	Houston Lighting and Power, Greens Bayou	294932	951326	1 30	121EVGL	1548	1947	W	N	С	N
(65	15	403	•	294902	951335		121EVGL	1429	1948	w	N	С	N
6	65	15	404	Houston Lighting and Power co, Greens Bayou	294930	951254		121EVGL	1500	1952	W	N	С	N°
(65	15	405		294929	951308	1	112CHCTU	135	1938	W	U	H	N
(65	15	406		294929	951309		121EVGL	890	1938	W	U	H	N
(65	15	411	City of Houston	294804	951250		11,2CHCT	350	1963	u	U	н	Y
•	65	15	412	Greens Bayou Estate City of Houston	294753	951300 `	١.٠	112CHCTL	332	1962	: W	P	М	Y
(65	15	423	Maxey Estates Gulf Oil Address	294845	951345	G	112CHCTL	229	1965	w	N	M	Y

Record of Communication To: Rudy Hodge, Water Engineer, City of Houston From: Ken Jensen, Fluor Daniel, Inc., Regarding City of Houston Water Supply, 5/30/95.

Date:

30 May 95

Time:

10:15 am PST

Call

From:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

To:

Rudy Hodge

Entity/Position:

Water Engineer - City of Houston

Phone #:

(713) 223-1095

Relevant Information:

Rudy gave the following information from the 1994 annual report of the City of Houston Water District:

Total 1994 pumpage:

123,704,270,000 gallons

Groundwater:

53,763,036,000 gallons

Surface Water:

69,930,236,000 gallons

Average pump rate per well at the Northeast station (total 7 wells) was 453,464,000 gallons per year (total for all wells 3,174,251,000 at Northeast cluster).

Average pump rate per well at the Heights station (total 9 wells) was 639,441,000 gallons per year (total for all wells 5,754,969,000 at Heights cluster).

There are 1.7 million people served by the Houston Water District.

Using these values, the following is calculated:

The annual population served by groundwater in Houston per year is 738,836. The number of persons on average served by each Northeast well is 6,232. The number of persons on average served by three Northeast wells is 18,695.

The number of persons on average served by each Heights well is 8,787. The number of persons on average served by three Heights wells is 26,362.

Phone #:

(713) 223-1095

Relevant Information:

Rudy gave the following information from the 1994 annual report of the City of Houston Water District:

Total 1994 pumpage:

123,704,270,000 gallons

Groundwater:

53,763,036,000 gallons

Surface Water:

69,930,236,000 gallons

Average pump rate per well at the Northeast station (total 7 wells) was 453,464,000 gallons per year (total for all wells 3,174,251,000 at Northeast cluster).

Average pump rate per well at the Heights station (total 9 wells) was 639,441,000 gallons per year (total for all wells 5,754,969,000 at Heights cluster).

There are 1.7 million people served by the Houston Water District.

Using these values, the following is calculated:

The annual population served by groundwater in Houston per year is 738,836. The number of persons on average served by each Northeast well is 6,232. The number of persons on average served by three Northeast wells is 18,695.

The number of persons on average served by each Heights well is 8,787. The number of persons on average served by three Heights wells is 26,362.

U.S. Environmental Protection Agency. Final Rule Hazard Ranking System, FR 51532-51667, December 14, 1990.



Friday December 14, 1990



Environmental Protection Agency

40 CFR Part 300 Hazard Ranking System; Final Rule



Record of Communication To: Tom Parker, Harris County Flood Control District, From: Ken Jensen, Fluor Daniel, Inc., Regarding Surface Water Usage in Areas Adjacent and Downstream of the S.P. Oliver Site, 6/02/95.

Date:

08 June 95

Time:

1:07 pm PST

Call

From:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

To:

Tom Parker

Entity/Position:

Harris County Flood Control District

Phone #:

(713) 684-4050

Relevant Information:

Tom stated that surface water and soils were not used as a resource within the 15-mile TSD of the S.P. Oliver site (sections of Hunting Bayou and Buffalo Bayou).

Record of Communication To: Dave Terry, Texas Natural Resources Conservation Commission, From: Ken Jensen, Fluor Daniel, Inc., Regarding Wellhead Protection Areas in vicinity of S.P. Oliver site.

Date:

23 May 95

Time: Call

8:45 am PST

From:

Entity/Position:

Dave Terry

Texas Natural Resources Conservation Commission (TNRCC)

Phone #:

(512) 239-4755 FAX 239-4760

To:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

Relevant Information:

Dave called to confirm that the site does not exist within a wellhead protection area, nor is it located within 4 miles of a wellhead protection area.

Record of Communication To: Johnnie Kennedy, TNRCC, Houston District Office From: Ken Jensen, Fluor Daniel, Inc., Regarding Current Agency (TNRCC) Activities at the S.P. Oliver Site, 5/17/95.

Date:

17 May 95 8:50 am PST

Time:

From:

Johnnie Kennedy

Entity/Position:

Texas TNRCC

Phone #:

(713) 625-7304

To:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

Relevant Information:

Johnnie called in response to a request for information on contaminant profile (types, levels, quantities of affected media) at the Wallisville Road site. The current TNRCC file ends at June, 1990; the most recent analytical report available was from 9/1/88, reflecting samples taken by Woodward-Clyde in August of 1988.

Main contaminants of concern at the site at 10s to 100s of ppm (mg/kg) were:

Lindane

Pentachloronitrobenzene

4,4'-DDT

4.4'-DDD

4,4'-DDE

Toxaphene was detected within site soils at levels over 1,000 ppm (mg/kg).

These levels have remained within site soils/sediments since the 1988 report was written; there is no record of the site having undergone remediation since the time of the Woodward-Clyde report.

There are unconfirmed reports of a surface removal action being performed in 1985/86 timeframe. No definitive file information has been found to date to substantiate this report.

TNRCC has undertaken a limited sampling of soils and sediments at the Wallisville road site; samples were taken in March/April 95 and are currently being processed through the State lab system.

No estimates of contaminant mass and/or affected soils volumes at the site have been found in the EPA or TNRCC files. Accordingly, preliminary estimates of volume will estimate contamination to 2 ft. over 25% of the site area and should be scaled back or increased if appropriate as more information is forthcoming.

Ecology and Environment, Inc., February 10, 1982. Memorandum from Imre Sekelyhidi, Environmental Engineer, E&E, Region VI; To: Dave Peters, Chief, Hazardous Wastes Section (Included in EPA File).

Ecology and Environment, Inc.

Region VI

MEMORANDUM

ONIN CORP-SPONIER

7XD000 602328

TO:

Dave Peters,

Chief Hazardous Wastes Section

FROM:

Imre Sekelyhidi, Environmental Engineer,

E&E. Region VI

THRU:

K. Malone, Jr., FITL Vin

DATE:

February 10, 1982

SUBJ:

Tasks Related to S.P. Oliver/Mustang/Seatrain (Old Olin) Site,

Houston, TX, TDD #F-6-8112-22

In response to the subject TDD were performed the following interrelated tasks:

1. Review of "Draft Remedial Action Plan, Wallisville Road Site, Houston, Texas."

The plan was reviewed first within the framework of the December 15, 1981, meeting between site and EPA presentatives, which Imre Sekelyhidi of our staff attended in accordance with TDD #F-6-8112-22, providing input in support of EPA observations concerning the plan.

The plan was also reviewed after the meeting, in preparation for the site visit, scheduled for January 13, 1982. Third, certain specific elements of the plan were discussed with site and state representatives at this meeting.

Attachment A briefly summarizes the result of the review.

2. Visit site with EPA and company representatives.

On the scheduled date weather conditions prevented the EPA representative from attending the meeting. As a consequense, E&E representatives, already in the area, were requested to attend the meeting, execute specific inspections accompanied by the participants and convey EPA directives to the participants. At the outset, as well as during the inspections E&E respresentatives, Imre Sekelyhidi and Debbie Vaughn made certain that their participation was not construed by the attendees to a representation of EPA, nor would any observations and statements made during the inspection be considered EPA positions, and the events which transpired would not obligate EPA in any way.

Attachment B briefly summarizes the results of the visit.

Roy F. Weston, Inc., 1985, Site Assessment Report on S.P. Oliver Pesticide Plant, Houston, Harris County, Texas, 10/21/85.

(Included in EPA File)

SPER CONTROL

Cerel's # TX01538

DOCUMENT CONTROL NO. TAT-20-F-01633

TDD NO. 6-8510-68

SITE ASSESSMENT REPORT

ON

OLLN CORP-SP CLIVER TXD 000607028

S. P. OLIVER PESTICIDE PLANT

HOUSTON, HARRIS COUNTY, TEXAS

Prepared for

EPA - REGION VI EMERGENCY RESPONSE BRANCH

Gerald Fontenot,
Deputy Project Officer

By

Roy F. Weston, Inc. Technical Assistance Team

DATE

October 21, 1985

My Deophoricage

Facsimile Transmission From: Tom Michel, Data Processing Manager, Harris-Galveston Coastal Subsidence District To: Ken Jensen, Fluor Daniel, Inc., Regarding Registered Wells Located Within a 4-Mile Radius of the Site, 5/19/95.

மு (

HARRIS - GALVESTON COASTAL SUBSIDENCE DISTRICT

1660 West Bay Area Blvd. Friendswood, Texas 77546 - 2640 Phone (713) 486 - 1105 Fax (713) 488 - 6510

(,

Fax Coversheet

To KEN JENSEN

Company : FLUOR DANIEL

12790 MERLY DR . SULTE 200

DALLAS, TX. 75252

Phone # : (214) 450 - 4100 Fax # : (214) 450 - 4101

From : Tom Michel - Data Processing Manager

Phone # : (713) 486 - 1105 Fax # : (713) 488 - 6510

Operator : Susan Brown

Pages : ____3 Including this cover page

ω(.

HARRIS-GALVESTON COASTAL SUBSIDENCE DISTRICT 1660 WEST BAY AREA BOULEVARD

FRIENDSWOOD, TX. 77546 PHONE: (713) 486-1105 FAX: (713) 488-6510

KEN JENSEN

DUE TO THE LARGE VOLUME OF REQUESTS FOR WELL DATA, IT HAS BEEN NECESSARY TO STANDARDIZE OUR OUTPUT FORMAT.

THE ENCLOSED PRINTOUT. LISTS ALL SITES ON WHICH A WELL HAS BEEN PERMITTED BY THE DISTRICT WITHIN 4.00 MILES OF THE FOLLOWING POINT IN THE ORDER OF DISTANCE FROM THAT CENTER POINT, (I.E. CLOSEST TO FARTHEST):

LATITUDE 29 DEG 47 MIN 20 SEC LONGITUDE 95 DEG 17 MIN 20 SEC

PROJECT NO.:

PLEASE NOTE: IT IS POSSIBLE THAT SOME OF THESE SITES MAY NOT ACTUALLY HAVE A PRODUCING WELL ON THEM. WE DO NOT GUARANTEE THAT THESE ARE THE ONLY WELLS WITHIN THE RANGE SPECIFIED, ONLY THAT THESE ARE THE WELLS THAT ARE PERMITTED WITH THE DISTRICT WITHIN THIS RANGE. WE REGRET THAT WE CANNOT CUSTOMIZE OUR OUTPUT TO INDIVIDUAL SPECIFICATIONS AND HOPE THAT THE ENCLOSED LIST WILL BERVE YOUR NEEDS.

SINCERELY,

TOM MICHEL
DATA PROCESSING HANAGER

HARRIS GALVESTON COASTAL SUBSIDENCE DISTRICT WELL RADIUS LISTING

ຕົ				WELL KAL	INS FISITH			•						
888	WELL NUMBE		LATITUDE	LONGITUDE	STATE #		DIST	ELEV	DIAM	DTFS	TOTAL DEPTH	YEAR DRILLED	APPROX. 93 PUMPAGE	
AGE.	2568	TEXAS PIPE LINE COMPANY	29-47-20	95-16-58	65-14-9		0.42	45	6,	815	845	58	0	
σ.	1675	PPG INDUSTRIEB, INC.	29-47-46	95-17-57	65-14-5		0.86	- 46	. 16	850	1125	63	. 0	
C	2738	(b) (6)	29-48-12	95-17-38	65-14-5		1.04	40	4	350	702	54	0	٠.
7 .	2996	EXXON COMPANY, U.S.A.	29-48-17	95-17- 4	65-14-6		1.12	45	g _:	0	0	83	0	
. .	2595	ALLIED FENCE CORPORATION	29-48- 4	95-18- 3	65-14-5		1.17	45	4	208	828	. 60	0	
Ç.	2596	ALLIED FENCE CORPORATION	29-48- 4	95-18- 3	65-14-5		.1.17	45	4	210	025	63	0 .	
(2918	STAR ENTERPRISE	29-47-47	95-16-21	65-14-6		1,23	40	4 ,	: 0	230	89 .	. 0	
٠.	- 5279	DELUTIS & BRASK	29-48-21	95-18- 3	64-14-5		1.41	45	4	60	500	68 .	0	
(1967	SOUTHERN PACIFIC TRANS. CO.	29-47-16	95-18-47	65-14-8		1.65	50	10	999	1200	81	0	
	1968	SOUTHERN PACIFIC TRANS. CO.	29-47-16	95-18-47	65-14-8		1.65	50	10	999	1200	54	0	
<u></u>	£751	KEY OIL COMPANY	29-48-46	95-17- 4	65-14-6		1.66	50	4.	0		83		
ăc	5259	GULF COAST KENWORTH	29-48-33	95-18-10	65-14-5		1.68	45	4	0	250	88		
B	4427	ROADWAY EXPRESS, INC.	29-47-36	95-15-45	65-14-6		1.82	40	4	282	302	81	0	
S.C.	2247	AMERICAN IND. LIFE INS. CO.	29-48-41	95-16-19	65-14-6		1.98	46	4	260	. 275	59	0	
PS1	1791	CINTAS CORPORATION	29-45-53	95-18-22	65-14-8.		٤. ٥٤	ó	6	347	434	63		
8,	1990	ANGELICA HEALTHCARE SERVICES	29-45-35	95-18- 2	65-14-8	•	2.14	. 44	18	810	1005	65	12,000,000	
ω 🦿	2611	BORDEN, INC. BAMA FOOD PRODUCTS	29-45-51	95-18-50	65-14-8		٤.40	41	. 8	. 0	595	28	•	
Σ.(2612	BORDEN, INC. BAHA FOOD PRODUCTS	29-45-51	95-18-50	65-14-8		2.40	41	8	:0	667	74	. 0	
. RO	- 4470	WILLIAMS BROTHERS CONST. CO.	29-46-43	95-1,5-17	65-1.4-9		2.43	35	5	348	380	90	1.071.700	
η (- /	1711	EXXON CHEMICAL COMPANY	29-45-12	95-16-45	65-14-9		2.51	35	10	635	701	47	36,700	
്യ	2008	MISSOURI PACIFIC RAILROAD CO.	29-49-33	95-17-26	65-14-6		2.52	50	16	769.	887_	64	. 0	
	2246	AMERICAN IND. LIFE INS. CO.	29-49-36	95-1G-43	65-14-6	•	2.67	48	. 4	200	£1,0	55	0	
	1718	COMET RICE MILLS, INC.	29-45-58	95-19-23	65-14-8		2.80	45	12	495	617	65	0	
) BY	1688	GULF COAST PORTLAND CEMENT CO.	29-45- 7	95-18-29	65-14-8	*	2.84	21	12	605	808	62	808,990	
σ,	2752	KEY OIL COMPANY	29-48-47	95-15-13	65-14-6		2.92	45	4	407	422	67	0	•
> -	5038	PARKER BROTHERS & CO., INC.	29-45-13	95-19- 1	65-14-8		3.07	36	4 .	359	382	67	0	
ÄΑ̈́,	1473	JACINTO CITY, CITY OF (1)	29-46- A	95-14-48	65-15-7	· .·	3.22	7	. 8	581	895	49	130,433,500	
		\mathbf{U}_{i}	•					•	•			• •		

PAGE.004

AY 19

					н.	A	R	R	I	S	- (Α	L	V	Ε	ε	T	0	1	1					
C	0	Α	s	T	A L		5	υ	В	S	1	D	Ε	N	(;	E	1	D	I	S	T	R	I	C	T
							u	EL	L	RAI	110	18	1	18	T	IN	G									

			·			•				•				•	
	NUMBE		INERS NAME	LATITUDE	LONGITUDE	STATE #	•	DIST	ELEV	DIAM	DTFS	TOTAL DEPTH	YEAR Drilled	APPROX 93 Pumpage	
	1084	HOUSTON, CI	ITY, OF LIL OI -	-> 29-47-43	95-20-10	65-14-4		3.25	50	24 :	999	1993	44	0	
	2239	TEX-TRUDE,	INC.	29-48-58	95-14-56	65-15-4		3.30	43	4	210	382	72	0	•
•	1086	HOUSTON, CI	17 OF WL 05 -	7 29-48- 5	95-20- 9	65-14-4		3.31	50	24	999	1980	49.	372,465,625	
	1026	HOUSTON; CI	ITY OF CLAIRMONT -	-> 29-50-17	95-17-11	65-14-3		3.36	51	16	593	807	.51	0	
,	1085	HOUSTON, CI	ITY OF WL 04 -	-7 29-48-15	95-20- 9	65-14-4		3.37	50	24	735	2080	49	372,465,685	•
	1475	JACINTO CIT	IY, CITY OF	29-46- 6	95-14-37	65-15-7		3.39	7	8	510	780	54	0	
4	1474	:JACINTO: CIT	IY, CITY OF D	29-46-21	95-14-30	65-15-7		3.41	7	. 8 .	390	1006	59	130,433,500	
	ė739	(b) (6)		29-48-57	95-14-48	65-15-4		3.42	45	4	400	ð	74	. 0	
	2478	WEINGARTEN,	, INC., J.	29-45- 4	95-19-19	65-14-8		3.42	40	6	814	905	57	0	•
	1709	REED TOOL	COMPANY	29-44-59	95-19-16	65-22-2		3.46.	49	7	858	1115	43	0	
	1951	NATIONAL VI	INEGAR COMPANY	29-46- 3	95-20- 8	65-14-7		3.50	45	4	486	506	68	3,514,250	٠.
	1952	NATIONAL V	INEGAR COMPANY	29-46- 3	95-20- 8	65-14-7		3.50	45	. 4	· 485	506	68	0	
•	4117	NATIONAL VI	INEGAR COMPANY	29-46- 3	95-20- 8	65-14-7		3.50	40	5	300	350	90	3,514,250	
	1087.	HOUSTON, C	ITY OF JUL 06	-> 29-49- 9	95-20- 4	65-14-4		3.73	55	24	999	1839	49	372,465,625	
	2369	PEOPLES NAT	IIONAL UTILITY CO.	29-48-31	95-14-16	65-15-4		3.74	٥	4	0	0	82		
	1976	SOUTHWEST	FABRICATING & WELDING	29-44- 2	95-17-31	65-22-2		3.76	35	8	485	517	68	•	
	2013	DICKSON IN	DUSTRIAL DISTRICT	29-44- 7	95-16-32	65-88-3		3.77	38	12	620	792	48	0	
	2270	GODDUILL IN	NDUSTRIES OF HOUSTON	29-48-29	9520-27	65-14-4	•	3.78	52	10	496	579	SS	460,000	
	3993	COODNILL II	NDUSTRIES OF HOUSTON	29-48-29	95-20-27	65-14-4		3.78	52	5	500	540	90	460,000	
	2128	SPÄRKLE ICE	E COMPANY	29-44-21	95-18-50	65-22-2		3.79	41	14	255	425	60	0	
	2334	FREEDMAN BE	ROTHERS PACKING CO	29-48-14	95-20-33	65~14-4		3.80	52	6.	360_	511	72		
-	1975	SOUTHWEST I	FABRICATING & WELDING	29-43-58	95-17-26	65-22-3	•	3.83	35	. 8	485	517	74	0	•
	1576	GENERAL POI	RTLAND, INC.	29-45-23	95-20- 5	65-14-7		3:83	50	14"	500	612	51	ð	
	2794		IBLE COLLEGE	29-49- 5		65-15-4		3.95	40	8	520	585	49	0	
		HOUSTON,C.			95-20- 1	65-14-4		3.96	61	24	999	1901	49	372,465,625	

Record of Communication To: Mark Leudke, Lance Robinson, TNRCC Fisheries Personnel Covering Galveston Bay From: Ken Jensen, Fluor Daniel, Inc., Regarding Recreational and Commercial Fishing Within Hunting Bayou and the Houston Ship Channel, 5/15/95.

Date:

15 May 95

Time:

9:20 am PST

Call

From:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

To:

Mark Leudke, Lance Robinson

Entity/Position:

TNRCC Fisheries personnel

Phone #:

ML:(713) 625-7690

LR:(713) 474-2811

Relevant Information:

Both references indicated no data were available for commercial/recreational yields from waters adjacent to the site. Commercial fishing does not take place on Whiteoak Bayou, Hunting Bayou, or Buffalo Bayou, the water body by which the first two are drained into Galveston Bay.

Stennie Meadours, TNRCC, 1990. Memo to Ernest Heyer, Head, Program Services Unit, Field Operations Division, TNRCC (Texas Water Commission). Subject: "Olin/Texas Water Commission Settlement Agreement; Sample Analysis Results", 5/17/90 (Included in EPA File).



FAX TRANSMITTAL

DATE: 5/17/95 NUMBER OF PAGES (including this cover sheet):

TO: Name Ken Jenson

FAX Number 714-975-2260

FROM:

TEXAS NATURAL RESOURCE CONSERVATION COMMISSION

Steve Hamm

Environmental Assessment Program

Region 12 - Houston Phone: (713) 625-7305 Fax: (713)-825-7324

NOTES:

SENT BY:

TÔ

5-17-95 ; 4:52PM ; TNRCC REGION 12→

714 975 2260;# 2/ 7

Texas Water Commission

INTEROFFICE MEMORANDUM

FILE

5-17-90

DATE: Ernest Heyer, Head, Program Services Unit

THRU : Field Operations Division

Stennie Meadours,

FROM : Emergency Response Coordinator, SER

SUBJECT: Olin/Texas Water Commission

Settlement Agreement Sample Analysis Results

Background

The manufacture of toxaphene, DDT and other pesticides was conducted at the former Olin site at 7621 Wallisville, Houston during the early 1940's until sometime in the late 1970's or early 1980's. Concentrations of toxaphene and other pesticides in the DOT group were documented by 1980-81 by Environmental Protection Agency (EPA) analytical activities. Initially, EPA pursued enforcement of the subject site and performed an historical aerial photographic analysis of the Olin site. Several solid waste management units including surface impoundments and surface dumps were identified by the EPA study (Photographic analysis of the Olin Hazardous Waste Site Houston, Texas, EPA June 1981, copy in Deer Park office). Sometime around 1984, the EPA referred the Olin site to the Texas Department of Water Resources for enforcement action. On June 16, 1988 the Texas Water Commission and Olin signed a settlement agreement which resulted from lawsuit NO. 394,086, Olin Corporation V. The Texas Water Commission. The United States Environmental Protection Agency. Eureka Investment Company. Southern Pacific Transportation Company and Houston Belt and <u>Terminal Railway Co</u>, in the 299th Judicial District Court of Travis County, Texas.

Current Status

On or about August 12, 1988, Stennie Meadours of the Deer Park office was assigned as district representative to monitor the remedial activities resulting from the Olin Corporation/Texas Water Commission Settlement Agreement of June 16, 1988. This agreement described remedial actions to be conducted by Olin Corporation adjacent to their previously owned and operated site at 7621 Wallisville Road, Houston. Site visits and monitoring of sampling and remedial activities at the 7621 Wallisville site was conducted on the following dates by the listed district personnel:

August 18, 22, 23, 24, and 26, 1988 - Stennie Meadours March 19, 1989 - Stennie Headours April 20, 1989 - Stennie Meadours

May 10, 1989 - Stennie Meadours, Glynna Leiper

May 16, 1989 - Eddie Elliot

May 23, 1989 - Stennie Meadours

June 9, 1989 - Stennie Meadours

August 25, 1989 - Stennie Meadours, Eddie Elliot

August 30, 1989 - Stennie Meadours, Ata Rahman and Mac Vilas

The documents and correspondence relevant to this report are attached and consist of the following:

- Attachment 1: Attorney General correspondence dated June 16, 1988 conveying the TWC/Olin Settlement Agreement and describing the dates of compliance as November 1, 1988 sampling, excavation and backfilling deadline, December 15, 1988 as deadline for submission of the engineer's certificate. (To date the engineer's certificate has not been submitted to the Deer Park office.)
- Attachment 2: Olin Corp.'s correspondence dated September 12, 1988 conveying Olin's Request for Proposal to perform the required work and acknowledging TWC concerns regarding the sampling that has already occurred.
- Attachment 3: Olin Corp's correspondence dated November 8, 1988 conveying the analytical results* of Olin's sample events which took place during August 23, 1988 thru August 29, 1988 and consisted of:
 - Four location along a line 20' south of Gloyd's residence running west. (As described 1. in B.2 of investigation plan and identified in results as OG-1 thru OG-4.)
 - 2. Seven locations on Gloyd property along the southern Gloyd property line. (As described in B.1 of investigation plan and identified in results as ED-1-B 2'-3' thru ED-7-C.)
 - Fifteen locations in ditch West of 7621 3. Wallisville site adjacent to Houston Belt and Terminals railway. (As described in A.1 and 2. of investigation plan and identified in results as ND-1-B thru ND-15A.)

*site drawing with sample locations identified included in this attachment by writer.

- Attachment 4: TWC, Deer Park office report dated February 10, 1989 conveying results of sample events that took place adjacent to the former Olin site and the Gloyd property on August 22, 23 and 26, 1988. Five samples of surface soils were collected and are identified by Chain of Custody Tag (COC) numbers.
- Attachment 5: TWC/Clin Technical Conference on February 15, 1989 where Olin stated proposed excavation to a depth of 3' with the exception of ND-2,4,6, where they planned to excavate to 4' and possibly deeper at ND 2 & 4. In regards to TWC sample results (COC'SW 14838) indicating pesticide contamination of 20 ppm in an area not planned for remediation activities. Olin officials stated they did not contemplate excavation beyond that which will be proposed in forthcoming plan addressing the ED and ND areas described in the plan.
- Attachment 6: Olin Letters of Transmittal dated February 28, 1989 conveying the draft remediation plan promised by Olin during the February 15, 1989 technical conference.
- Attachment 7: TWC telephone memo dated March 29, 1989 documenting a conversation between Tim Chaney (TWC) and Verill Norwood (Olin) in which Tim Chaney expressed to Mr. Norwood that Olin activities and Remediation Plan to date did not conform to the investigation plan included in the Settlement Agreement. Areas where additional sampling was needed to determine the vertical extent of contamination were identified by Mr. Chaney.
- Attachment 8: Woodward-Clyde Consultants correspondence dated April 3, 1989 conveying a copy of the final remediation plan and expressing the incorporation of all Mr. Chaney's comments to Mr. Norwood.
- Attachment 9: Attorney Generals correspondence dated April 14, 1989 regarding Ms. Gloyd's release authorizing access to and sampling activities on her property and authorizing the use of a power driven augur in certain sampling points.

- Attachment 10: Tim Chaney (TWC) telephone memo documenting a conversation with Brian Berwick concerning notification of the SER Office prior to sampling or excavation work.
- Attachment 11: Attorney General's faxed copy dated May 25, 1989 an unsigned version of the <u>Release and Access</u>
 <u>Agreement</u> prepared for Ms. Opel Gloyd's signature.
- Attachment 12: TWC Service Request dated May 23, 1989 in which Ms. Opel Gloyd requests:
 - •Information regarding Wallisville/Olin site remedial work
 - Analysis results of samples collected on the Gloyd property and a TWC citizens request for assistance requesting soil sample collection and analyses on the Gloyd property.
- Attachment 13: TWC Woodward-Clyde Consultants correspondence dated May 25, 1989 recommending a layer of stone approximately 10 to 12 inches be placed in the excavated ditch provided that it is underlain by 3 feet of clay backfill. In addition, the correspondence states that the caliche used as a road bed for the Wallisville excavations is considered adequate for use as a cover for the clay.

Attachment 14: Photographs (to be included under separate cover).

As requested by Mrs. Gloyd on May 23, 1989, on August 25, and 30 1989, eleven soil samples were collected in Mrs. Gloyd's yard adjacent to the area remediated. The samples were analyzed for pesticides, toxaphene and BHC (lindane). The results of the sample analysis are shown in the table entitled <u>Ulin/Gloyd Analyses</u> Results and a map of sample locations is attached to the table.

Action Requested

This incident of a documented release of a toxic pesticide is being referred to the TWC hazardous waste screening committee for evaluation and a recommended course of action. Three possible actions which may be considered are:

1. Require additional investigative and remedial actions of Olin Corp.

714 975 2260;# 6/

File April 19, 1990 Page 5

Olin/Gloyd Analyses Results

Chain of Custody Tag #	SW02637	SW02638	SW02639	SW02640	SW02641	SW02642	SW02643	SW02644	SW02645	SW02646	SW02647
Date	8-25-89	8-25-89	8-25-89	8-25-89	8-30-89	8-30-89	8-30-89	8-30-89	8-30-89	8-30-89	8-30-89
Chemical	#1	#2	#3	• #4	#5	# 6	#7	#8	#9	#10	#11
Toxaphene	*	*	8.2	49.5	21.0	1.3	*	0.6	156.0	0.4	<0.05
Deildrin	0.005	0.06	0.003	ata dan	0.03	0.004	0.01	· 	~-	0.003	
Lindane	<0.001	<.001	<.001	<.001	<.001	<.001	<.001	<.001	<.001	<.001	<.001
Chlordane											0.02
PP DDE	0.08	1.0	.06	1.6	0.1	, 	0.13	20 44	. 	0.09	· • • • • • • • • • • • • • • • • • • •
PPDDT	0.07	2.0	400 880	*****			0.09				0.15
OP'DDT		~~	-	•							-

All units in ppm.
Chain of Custody Tags are attached.
*Unable to detect due to high background interference.
**Sample location map attached.

- 2. Execute a state funded emergency action from either the Texas Spill Response Fund or the Hazardous Waste-Disposal Fee Fund.
- 3. Consider the source of the contamination, the former pesticide manufacturing site, for ranking on the National Priorities List. (To date this office is unaware of any investigations conducted at the manufacturing site.)

Signed:

Stennie a. Meadours

Stennie A. Meadours

Emergency Response Coordinator

Hazardous and Solid Waste

Southeast Region

SM/ja

Now in North (612) 259-2505

FLUOR DANIE

Record of Communication To: Shannon Breslin, Texas Natural Heritage Program - Resource Protection Division. From: Ken Jensen, Fluor Daniel, Inc., Regarding Endangered Species Within the TDL of the S.P. Oliver Site, 5/23/95.

Date:

23 May 95

Time:

11:55 am PST

Call

From:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

To:

Shannon Breslin

Entity/Position:

Graduate Student/Employee Texas Natural Heritage Program -

Resource Protection Division

Phone #:

(512) 912-7021

Relevant Information:

Shannon looked at endangered species both at the site and for 15 miles downstream of the site. She came up with three species which could conceivably use this area as habitat, although she described the likelihood of finding these species as "very unlikely". The species were:

Prairie Dawn

flowering annual


Texas Windmill Grass


grass species


Houston Machaeranthera


grass species

U.S. Department of the Interior, Fish and Wildlife Service, National Wetlands Inventory maps: Settegast, TX; Jacinto City, TX; Park Place, TX; Pasadena, TX.










U.S. Geological Survey, 7.5-minute topographic maps: Settegast (1982), Jacinto City (1982), Park Place (1982) and Pasadena (1983), Texas.



2995-431


COLORADO 80225, OR RESTON, VIRGINIA 22092


ND SYMBOLS IS AVAILABLE ON REQUEST


N2945-W9515/7.5

1982

DMA 6943 IV SE-SERIES V882








Texas Water Resources Data, Water Year 1991, Volume 2. San Jacinto River Basin, Brazos River Basin, San Bernard River Basin, and Intervening Coastal Basins. U.S. Geological Survey Report TX-91-2.



Water Resources Data Texas Water Year 1991

Volume 2. San Jacinto River Basin, Brazos River Basin, San Bernard River Basin, and Intervening Coastal Basins



U.S. GEOLOGICAL SURVEY WATER-DATA REPORT TX-91-2 Prepared in cooperation with the State of Texas and with other agencies

08075770 HUNTING BAYOU AT INTERSTATE HIGHWAY 610, HOUSTON, TX

LOCATION.--Lat 29°47'35", long 95°16'04", Harris County, Hydrologic Unit 12040104, on left bank at downstream side of downstream service road bridge of Interstate Highway 610 in northeast Houston and 8.8 mi upstream from mouth.

ORAINAGE AREA.--16.1 mi². Prior to Oct. 1, 1973, 16.8 mi². Oct. 1, 1973, to Sept. 30, 1978, 14.7 mi². Oct. 1, 1978, to Sept. 30, 1987, 15.8 mi². Changes due to storm sewer relocations and addition or relocation of ditches.

WATER-DISCHARGE RECORDS

PERIOD OF RECORD. -- April 1964 to current year. Prior to October 1973, published as "U.S. Highway 90-A, Houston".

GAGE.--Water-stage recorder and crest-stage gage. Datum of gage is National Geodetic Vertical Datum of 1929, 1959 adjustment; unadjusted for land-surface subsidence. Prior to Oct. 1, 1972, water-stage recorder at site 1,800 ft upstream at same datum.

REMARKS.--Records good except those for estimated daily discharges, which are fair. Low flow is largely maintained by sewage and industrial effluent. The stage-discharge relationship is affected by seasonal vegetal growth during most years. Recording rain gage at station. Stage and rainfall radio-telemeter at station, is operated by the Harris County Flood Control District.

AVERAGE DISCHARGE.--27 years, 23.6 ft³/s (17,100 acre-ft/yr).

EXTREMES FOR PERIOD OF RECORD.--Maximum discharge, 3,470 ft³/s June 26, 1989 (elevation, 39.91 ft); minimum daily discharge, 0.88 ft³/s Aug. 24, 1971.

EXTREMES FOR CURRENT YEAR. -- Peak discharges greater than base discharge of 1,000 ft³/s and maximum (*):

Date	Time	Discharge (ft³/s)	Elevation (ft)	Date	Time	Discharge (ft³/s)	Elevation (ft)
Jan. 10	1130	1,530	33.23	Apr. 5	1700	1.630	33.64
Jan. 15	0130	*1,900	*34.75	Apr. 14	1800	1.290	32.16
Jan. 18	1330	1,070	31.05	June 15	1300	1.070	31.07

Minimum daily discharge, 3.4 ft³/s Oct. 16, 31.

DISCHARGE, CUBIC FEE	PER SECUND, WATER	R YEAR OCTOBER 1990 TO SEPTEMBER 1991	
•	DAILY MEAN	N VALUES .	

DAY	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
1 2 3 4 5	3.6 3.8 5.1 13 17	3.5 4.4 12 11 8.7	5.6 5.2 4.9 4.9 4.7	8.4 185 202 24 15	11 11 10 382 164	76 20 13 11	7.0 6.1 5.7 167 731	5.5 7.0 5.1 5.3 4.9	4.7 4.2 7.6 12 4.5	8.3 8.8 14 33 13	5.6 5.4 5.4 7.1	27 44 34 11 42
6 7 8 9 10	8.7 10 4.6 18 11	4.6 4.0 75 140 14	7.1 14 7.0 10 7.3	53 24 14 90 650	34 20 16 15	9.7 9.6 8.5 7.6 7.4	209 33 16 12 10	4.4 4.8 19 13 5.9	4.0 28 70 51 29	8.6 8.8 7.0 6.4 6.4	5.8 25 14 7.0 5.6	104 66 39 9.2 8.1
11.	5.8	8.4	5.6	85	13	7.4	117	5.6	24	6.3	5.5	6.7
12	4.2	6.9	5.0	26	12	7.7	34	4.9	39	5.9	5.8	67
13	3.9	6.2	4.9	18	12	6.9	17	4.6	10	5.8	6.0	63
14	3.8	5.3	5.1	121	11	6.8	454	4.8	13	5.7	8.8	25
15	3.7	5.0	4.9	730	10	24	186	40	407	5.8	13	8.2
16	3.4	5.0	4.7	53	9.8	57	35	32	74	5.5	60	7.4
17	96	4.7	4.9	25	11	36	61	22	82	5.4	16	6.2
18	52	4.8	10	434	11	14	165	11	38	7.0	8.8	11
19	7.2	5.0	5.6	117	31	9.6	26	11	27	11	20	8.6
20	5.0	4.9	5.1	32	13	8.4	14	9.8	18	6.1	6.0	5.6
21	92	4.9	9.1	20	282	8.8	9.9	9.0	22	5.7	5.2	5.4
22	35	17	7.1	19	57	7.9	8.7	13	19	5.8	9.9	6.5
23	8.0	17	6.1	15	21	7.3	7.8	14	15	5.2	5.5	5.2
24	5.4	8.0	5.7	24	15	7.1	7.0	6.5	e14	6.4	6.4	9.2
25	4.5	6.8	6.3	16	19	6.7	6.9	5.9	e27	11	4.6	18
26 27 28 29 30 31	4.1 3.8 3.8 3.6 3.5 3.4	6.7 8.8 6.2 4.9 4.8	47 95 13 9.6 8.4 8.2	14 14 13 13 13	15 12 20	6.6 6.3 8.8 33 8.2 6.8	6.4 6.6 6.0 5.6 5.0	4.9 4.7 4.5 43 15 6.4	e43 47 16 14 9.5	7.7 5.5 5.0 21 17 5.8	4.0 3.6 3.7 3.5 3.6 5.6	5.6 4.8 4.5 6.8, 5.7
TOTAL	446.9	418.5	342.0	3080.4	1251.8	459.1	2375.7	347.5	1173.5	274.9	297.4	664.7
MEAN	14.4	13.9	11.0	99.4	44.7	14.8	79.2	11.2	39.1	8.87	9.59	22.2
MAX	96	140	95	730	382	76	731	43	407	33	60	104
MIN	3.4	3.5	4.7	8.4	9.8	6.3	5.0	4.4	4.0	5.0	3.5	4.5
AC-FT	886	830	678	6110	2480	911	4710	689	2330	545	590	1320

WTR YR 1991 TOTAL 11132.4 MEAN 30.5 MAX 731 MIN 3.4 AC-FT 22080

e Estimated

08074000 BUFFALO BAYOU AT HOUSTON, TX

LOCATION.--Lat 29°45'36", long 95°24'30", Harris County, Hydrologic Unit 12040104, on right bank at downstream side of bridge on Shepherd Drive in Houston and 0.8 mi upstream from Waugh Drive.

DRAINAGE AREA. -- 358 mi2, unadjusted for basin boundary changes.

WATER-DISCHARGE RECORDS

PERIOD OF RECORD.--May 1936 to September 1957, October 1957 to December 1961 (high-water records and discharge measurements), January 1962 to September 1975, October 1975 to current year (high-water records and discharge measurements).

REVISED RECORDS. -- WSP 1732: Drainage area (former site).

GAGE.--Water-stage recorder and crest-stage gages. Datum of gage is 1.36 ft below National Geodetic Vertical Datum of 1929, 1973 adjustment; records unadjusted for land-surface subsidence. Prior to June 19, 1936, nonrecording gage, and June 19, 1936, to Jan. 16, 1962, water-stage recorder at site 0.8 mi downstream at 4.08-feet lower datum. Jan. 17, 1962, to Sept. 30, 1973, auxiliary water-stage recorder 0.8 mi downstream. Water-stage recorder at Main Street (station 08074600) used as auxiliary gage after Sept. 30, 1973.

REMARKS.--Records fair. Although floodflows are regulated by Barker and Addicks Reservoirs (stations 08072500 and 08073000) located 26.3 and 26.8 mi upstream, respectively, flood peaks from the urbanized areas below these reservoirs are often independent of the regulation. Discharge is computed using a stage-fall-discharge relationship for all storms that produce peak discharges above 2,000 ft'/s. Discharges below 1,000 ft'/s are computed or estimated following designated storm periods only. Low flow is mostly sustained by sewage effluent from Houston suburbs. Gage heights are affected by tides, backwater from Whiteoak Bayou, and other streams. Gage-height telemeter at station.

AVERAGE DISCHARGE.--8 years (water years 1936-44) unregulated, 272 ft³/s (197,100 acre-ft/yr); 26 years (water years 1944-57, 1962-75) regulated, 274 ft³/s (198,500 acre-ft/yr).

EXTREMES FOR PERIOD OF RECORD.--Maximum discharge, 10,900 ft³/s Aug. 30, 1945 (gage height, 28.82 ft), at site 0.8 mi downstream at present datum; maximum gage height, 30.00 ft May 18, 1989, at current site; minimum daily, 1.3 ft³/s May 24, 1939, Nov. 5, 1950, occurred prior to urban development and accompanying sewage effluent releases.

EXTREMES OUTSIDE PERIOD OF RECORD.--All flood data at site 0.8 mi downstream at present datum. Maximum gage height since at least 1835, 49.0 ft Dec. 9, 1935 (discharge, 40,000 ft²/s); furnished by engineer for Harris County. Flood of May 31, 1929, reached a gage height of 43.5 ft (discharge, 19,000 ft²/s), at bridge on Capitol Avenue, affected by bridge; furnished by city of Houston.

EXTREMES FOR CURRENT YEAR.--Maximum discharge, 4,840 ft³/s Apr. 5 at 1900 hours (gage height, 19.28 ft); minimum discharges not determined (affected by tides).

DISCHARGE, CUBIC FEET PER SECOND, WATER YEAR OCTOBER 1990 TO SEPTEMBER 1991 DAILY MEAN VALUES

DAY	ОСТ	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
1												
Ž				1240	·							
3				2000								
4					2180		939					
Ś					1720		2680					
,					1720		2000					
6							2300					1710
7								1700				1070
8		337						2030	- 131			1070
ğ		1190		1060				1100				
10				3210								
10				3210				-,				
٠.				074			1270					
11				874			1370					
12												
13							.===					
14				1090			1780					
15				3300			2180		1280			
16												
17							643		1550			
18				2190			2050					
19				1320								
50									853			
21			,		1390							
22												
23					-							
24												'
25												
26												
27												
28												
žš												
30												
31												
31					•••							
CAL	YR 1990	TOTAL	MEAN	MAX		MIN	AC-FT					
	YR 1991	TOTAL	MEAN	MAX		MIN	AC-FT					

U.S. Department of Commerce County and City Data Book, 1994.

12th Edition

County and City Data Book





ASeusimeliansiamensundensii

U.S. Department of Commerce Economics and Statistics Administration BUREAU OF THE CENSUS

Table B. Counties - Group Quarters Population and Households

															
	Group que	arters populat	tion, 1990					1	Households, 1990						
						ļ	Perce	nt –				By type-			
ļ						ļ		With 1 or			Family hous			}	
County		,	·				·	more per-			Married-coup		Female hous	enolder*	
					Percent	Per- sons		sons 65		Percent with		Percent with		Percent with	:
		College	Nursing	M	change, 1980-	per house-	One	years and	T-1-12	chil-		own chil-	T-4-1	own chil-	Nonfamily
	Total	dormitories	homes	Number	1990	hold	person	over	Total ²	dren ³	Total	dren3	Total	dren ³	households
	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46
TEXAS—Con.	1 278		342	6 492	-6.2	2.53	29.3	38.1	4 544	42.9	3 444	41.0	919	49.2	4.05-
FallsFanninFayette	777	=	749 354	9 691 8 101	4.6 8.2	2.48 2.43	26.4 28.4	35.8 39.4	7 057 5 736	41.3 42.6	6 020 4 945	40.0 42.5	· 712	53.5 44.9	1 970 2 759 2 385
Fisher	69 123	-	67 93	1 892 2 982	-14.2 -9.8	2.52 2.81	25.8 22.7	37.8 32.5	1 394 2 339	40.8 47.6	1 180 2 119	38.6 47.2	146 138	53,4 58.0	504 714
Foard	37 4 349	26	37 558	739 70 424	-14.1 76.8	2.38 3.14	31.0 13.6	43.2 11.5	496 59 435	41.1 63.4	408 50 517	42.9 63.7	73 6 895	34.2 64.6	237 11 080
Freestone	141 416		133 284	3 017 6 063	15.3 8.1	2.54 2.54	23.6 26.7	33.4 35.1	2 307 4 434	41.2 47.2	2 017 3 665	40.3 46.7	258 641	47.7 53.8	742 1 704
Frio	275 40	-	120 30	4 129 4 502	2.2 7.4	3.20 3.13	18.1 18.4	25.7 21.5	3 366 3 669	55.8 57.5	2 586 3 195	54.4 58.2	617 305	58.2 56.4	817 878
Galveston	2 606 63	661	890 62	81 451 1 822	17.6 -1.1	2.64 2.79	24.3 22.4	20.8 31.2	58 334 1 379	50.6 48.9	45 519 1 230	48.6 47.6	10 043 120	60.4 64.2	23 083 427
Gillespie	685 3	-	399	6 711 456	28.6 17.8	2.46 3.17	24.2 13.4	40.2 13.8	5 092 371	36.9 57.1	4 684 332	35.1 57.2	322 21	58.4 66.7	1 722 79
Goliad	69 316 256	=	59 246 181	2 208 6 231 9 548	24.3 4.7 -6.6	2.68 2.71 2.48	22.9 25.8 25.8	32.5 34.2 31.3	1 694 4 592 7 031	46.8 46.5 44.8	1 428 3 747 6 089	45.6 45.3 42.5	214 630 723	56.1 55.1 63.3	536 1 670 2 539
Grayson	2 440	864	1 297	36 847	8.5	2.51	25.2	29.0	26 800	46.5	22 192	44.3	3 634	58.8	9 999
Gregg	2 294 2 411	852	1 151 127	40 027 6 040	11.5 24.4	2.56 2.72	25.9 23.7	24.6 31.4	28 579 4 437	50.0 48.8	22 796 3 442	48.2 51.9	4 588 723	59.7 39.7	11 523 1 575
Guadalupe	1 324 739	577 321	433 256	22 663 11 703	44.0 -5.5	2.80 2.90	19.2 21.6	23.9 (26.1	18 013 8 947	50.2 52.8	14 896 7 494	48.2 52.0	2 327 1 061	61.9 59.4	4 889 2 816
Hall	46 276] -	46 257 72	1 669 3 250 2 112	-23.3 -5.1 -6.9	2.31 2.29 2.73	33.7 30.4 21.9	45.8 42.1 24.2	1 088 2 208 1 642	39.9 37.5 52.7	947 1 905 1 467	38.2 36.3 52.1	112 225 117	51.8 44.4	569 1 027
Hansford Hardeman	75 144	-	98	2 101	-15.1	2.45	30.3	40.3	1 443	47.7	1 189	46.1	178	72.6 50.0	481 666
Hardin	297 29 144	5 642	242 7 886	14 693 1 026 448	7.0 18.0	2.79 2.72	19.2 26.2	24.1 14.5	11 735 708 831	50.0 54.9	10 012 541 226	50.2 54.4	1 355 127 240	51.8 60.2	3 004 318 987
Harrison	1 434 90	718	518 84	20 705 1 332	-2.1	2.71 2.66	23.0 20.4	27.4 26.4	15 729 1 041	49.7 46.1	12 582 990	48.8 45.6	2 659 32	53.1 56.3	5 085 293
Hays	133 6 152 52	4 621	122 373 47	2 753 22 218 1 348	76.6	2.43 2.68 2.72	27.7 22.3 22.0	41.5 16.0 24.6	1 957 14 443 1 011	42.7 51.7 53.6	1 754 12 331 912	41.1 51.8 52.9	153 1 493 64	58.2 55.9 76.6	796 7 722
HemphillHenderson	983 3 808	245 335	556 1 136	22 947 103 479	42.6	2.51 3.67	22.6 13.4	34.0 25.8	17 379 88 615	39.7 61.1	14 872 69 966	37.2 61.7		56.5 60.8	312 5 582 14 899
Hill	960	125	491	10 268	6.0	2.55	25.7	37.1	7 502	42.5	6 320	41.6	910	48.0	2 855
Hockley	553 338	409	77 254	7 988 11 137	6.2 64.8	2.96 2.57	18.9 19.2	23.3 27.8	6 446 8 778	55.0 43.3	5 594 7 796	53.8 42.1	652 695		1 588 2 390
Houston	427 1 837 2 195	105	377 293 457	10 965 7 792 11 477	15.1 8.2 -4.1	2.59 2.51 2.63	24.2 26.4 23.7	29.6 37.0 27.8	8 033 5 646 8 463	47.9 44.3 47.7	6 899 4 372 6 817	46.7 42.0 45.1	858 1 047 1 298	57.1 55.9	2 862 2 127 2 911
HowardHudspeth	107	195 790	530	946 24 075		2.97 2.61	22.1 23.9	23.8 26.4	748 17 673	56.1 47.2	641 14 729	54.4 45.4			221 6 325
Hutchinson	305	120	108	9 642		2.63	22.5	28.7	7 343	48.7	6 420	47.5	623	58.6	2 362
Irion	116	[-	77	601 2 725	18.5 -5.8	2.71 2.52	19.1 26.1	26.5 33.8	485 1 927	50.1 48.3	433 1 750		135	70.4	116 773
Jackson	141 366 54] =	111 337	4 833 11 427 779	6.7	2.67 2.69 2.43	23.7 21.9 28.6	33.3 31.0 34.0	3 680 8 827 533	45.8		43.9		58.9	
Jeff Davis Jefferson Jim Hogg	4 443	746	1 819	90 520 1 675	.3	2.60 3.05	26.1 20.4	26.9 31.7	64 768 1 326	47.9	49 880 1 040	46.0	12 111	. 57.5	25 635 340
Jim Wells	476 1 879		393 893	11 979 33 462	7.3	3.11 2.85	18.2 17.1	25.8 20.7	9 647 26 782	53.9	7 809	55.3	1 479	54.6	2 317
Jones	394	_	361	6 180	-2.9	2.60	24.4	34.2	4 574	46.4	3 944	46.6	453	37.7	1 571
Karnes	237 1 273 384		230 572 253	4 337 17 827 5 342	35.5	2.82 2.86 2.66	23.7 19.0 19.7	35.3 24.2 28.2	3 284 14 179 4 216	51.4			1 975	58.0	1 047 3 656 1 149
Kenedy	11 25	1 -	253	145 399	-14.2	3.10 2.47	16.6 26.6	22.1 35.3	112 283	43.8	105	44.8	3	-	22
Kerr	2 035 69	343	499 55	14 384 1 624	28.8 3.8	2.38 2.50	27.4 24.4	40.1 37.5	10 183 1 214	39.5	8 567	35.5	1 358	61.6	4 196
King	-	-	-	124	-19.5	2.85	14.5	13.7	108	1	104	56.7	1	100.0	19
Kinney	1 227	840	103	1 187 10 058 1 887	-2.2	2.59 2.89	26.7 21.8	40.2 21.9 38.8	877 7 268 1 338	53.2	5 819	52.6	1 228	60.3	2 631
Lamar	106 971 142	195		16 798 5 488	6.9	2.51 2.56 2.72	28.8 25.0 24.1	38.8 31.5 34.7	12 448 4 129	46.2	10 203	45.2	1 842	52.6	
LambLampasasLa Salle	168	-	145	5 058 1 701	14.6	2.64 3.05	23.2 21.6	29.5 31.8	3 751 1 354	49.8 47.6	3 198 1 046	48.5	451	58.8	1 268
Lavaca	360 520	- 1	320 136	7 349 4 706	2.8	2.49	27.5	40.7 30.2	5 212 3 447	42.7	4 480	41.2	597	56.6	2 077
		<u> </u>		L	<u> </u>	L		L	<u> </u>		L	<u> </u>	<u> </u>	<u>L</u>	

¹Includes persons in other institutional and noninstitutional group quarters, not shown separately, ely. ³Under 18 years. ⁴No husband present.

2Includes male householder families with no wife present, not shown

REFERENCE 23

Land Resources Laboratory Map Series: Land and Water Resources - Houston-Galveston Area Council. Bureau of Economic Geology, 1975.

LAND RESOURCES LABORATORY MAP SERIES

Land and Water Resources – Houston-Galveston Area Council

by

A. E. St. Clair, C. V. Proctor, Jr., W. L. Fisher, C. W. Kreitler, and J. H. McGowen



BUREAU OF ECONOMIC GEOLOGY
THE UNIVERSITY OF TEXAS AT AUSTIN
AUSTIN, TEXAS 78712
C. G. GROAT, ACTING DIRECTOR
1975

Table 2. Ages and stratigraphic names of natural depositional systems, HGAC.

GEO	GEOLOGIC AGE (MILLION OF YEARS)		EOLOGIC AGE (MILLION OF		STRATIGRAPHIC NAME	DEPOSITIONAL SYSTEMS, HGAC	LAND AND WATER RESOURCE UNITS, HGAC
	PERIOD	Holocene		Alluvium	Fluvial; Deltaic; Marsh-Swamp; Bay-Lagoon; Barrier-Strandplain	B1, B2, B3, B4, B5, B6; B7, F8; D1, D2, D3, D4; F1, F2, F3, F4, F5, F6, F7, F11, F12; C1, C2, C3, C4	
	QUATERNARY PE		.2	Beaumont Formation (including Ingleside sand)	Fluvial-Deltaic; Barrier-Strandplain	A2, A4; A1	
	ATERI	Pleistocene		Lissie Formation	Fluvial (meanderbelt)	A2, A3, A9	
4	g)	7	2	Willis Formation	Alluvial Fan, Braided Streams	A1, A8, A3, A6	
ZOIC ERA	۵	Pliocene	3	Goliad Formation (does not occur in HGAC)			
CENOZOIC	PERIOD	Miocene 11		Fleming Formation	Fluvial	A4, A5	
0		??	25	Catahoula Formation	Fluvial-Deltaic	A7, A2	
	TERTIARY	Oligocene	40	Vicksburg Formation (subsurface only)			
		Eocene		Jackson Group	Fluvial-Deltaic	A2, A7	

across northern Walker County. Younger fluvial deposits (Fleming and Willis Formations) in northwestern and northeastern HGAC were deposited in the channels and on the floodplains of Tertiary rivers.

Pleistocene systems.—Coastward of the outcrop belt of Tertiary fluvial deposits is a large area underlain by Pleistocene alluvial fan deposits composed of sand and gravel (Willis Formation). These were formed by high-gradient braided streams that flowed coastward from the Tertiary uplands to deposit coalescing alluvial fans.

Coastward of the alluvial fans, younger Pleistocene meanderbelt fluvial sands and muds (Lissie Formation) grade into fluvial-deltaic deposits (Beaumont Formation) which extend almost to the present coastline. This fluvial-deltaic

system, which is characterized by elongate distributary channel sands and interdistributary muds, extends across the central and southern HGAC. Near the present coastline, Pleistocene marinedeltaic sands mark the terminus of the relict delta system. Pleistocene barrier-strandplain sands (Ingleside sands) occur in a discontinuous belt in the southeastern part of HGAC.

Holocene-Modern systems.—Holocene-Modern fluvial systems extend across the outcrop of relict Tertiary and Pleistocene deposits. These fluvial systems are composed of sediments deposited by the Colorado, Brazos, San Jacinto, and Trinity Rivers during the past 20,000 years. Fluvial processes are still active in these systems, and fluvial sand and mud are presently being deposited. In the lower reaches of these fluvial systems, deltaic deposition is occurring along natural levees,

REFERENCE 24

U.S. Geological Survey, Water Resources Investigations Report 87-4153. Ground-Water Withdrawals and Changes in Ground-Water Levels, Ground-Water Quality, Etc. in the Houston District, Texas, 1980-84.

GROUND-WATER WITHDRAWALS AND CHANGES IN GROUND-WATER QUALITY, AND LAND-SURFACE SUBSIDENCE IN THE HOUSTON DISTRICT. TEXAS, 1980-84

U.S. GEOLOGICAL SURVEY
Water-Resources Investigations Report 87-4:153



Prepared in cooperation with the CITY OF HOUSTON and the HARRIS-GALVESTON COASTAL SUBSIDENCE DISTRICT

INTRODUCTION

The purpose of this report is to provide information about ground-water withdrawals, changes in ground-water levels, ground-water quality, and trends in land-surface subsidence in the Houston district during 1980-84. Some data collected prior to 1980 and during the early spring of 1985 are presented to establish long-term trends and relations.

The Houston district, as described in this report, includes all of Galveston County and parts of Brazoria, Chambers, Fort Bend, Harris, Liberty, and Waller Counties (fig. 1). Many homeowners, well drillers, industrial-plant managers, and State and municipal officials provided information for this report. Financial support was provided by the city of Houston and the Harris-Galveston Coastal Subsidence District in a cooperative agreement with the U.S. Geological Survey.

GEOHYDROLOGY OF THE STUDY AREA

The geohydrologic units discussed in this report primarily are the Chicot and Evangeline aquifers. The Jasper aquifer also underlies the Houston district, but contains water of poor quality except in the northern part of the district. Only two wells presently are known to yield water from the Jasper aquifer in Harris County. These aquifers are composed of sedimentary deposits in the Coastal Plain physiographic province. The province is a broad plain underlain by a southeasterly thickening wedge of layered beds of clay, silt, sand, and gravel. The geologic formations in the study area are, from oldest to youngest: The Oakville Sandstone and Fleming Formation of Miocene age; the Goliad Sand of Pliocene age; the Willis Sand, Bentley Formation, Montgomery Formation, and Beaumont Formation of Pleistocene age; and alluvium of Quarternary age. The relation among the geohydrologic units and the geologic formations is given in table 1. A generalized geohydrologic section of the Chicot, Evangeline, and Jasper aquifers through Montgomery, Harris, Brazoria, and Galveston Counties is shown in figure 2.

Chicot Aquifer

The Chicot aquifer includes all deposits from the land surface to the top of the Evangeline aquifer. The Chicot aquifer is composed of the Willis Sand, Bentley Formation, Montgomery Formation, Beaumont Formation, and Quaternary alluvium. The altitude of the base of the Chicot aquifer is shown in figure 3. The discontinuous sand and clay layers of the Chicot aquifer in some parts of the study area are separated into an upper and lower unit (Jorgensen, 1975, p. 10). When the upper unit of the Chicot aquifer cannot be defined, the aquifer is undifferentiated. The Chicot aquifer is under conditions except in the northern part of the district. Generally, in southeastern Harris County and most of Galveston County, the Chicot aquifer contains a thick sand section that has a relatively large (as much as 75 ft/d) hydraulic conductivity (Jorgensen, 1975, p. 15). This sand unit has been intensely pumped and is known locally as the Alta Loma Sand (Alta Loma Sand of Rose, 1943). In this area, there also is another sand unit within the Chicot aquifer referred to as the middle Chicot aquifer. The Chicot aquifer is the main source of ground water in Galveston and southern Harris Counties.




Figure 2.--Correlation of hydrologic units from northern Montgomery County to the Gulf of Mexico.

Evangeline Aquifer

The Evangeline aquifer, composed of the Goliad Sand and the upper part of the Fleming Formation, is similar in lithology to the Chicot aquifer. One difference between the two aquifers is that the Evangeline aquifer generally has a smaller hydraulic conductivity than does the Chicot aquifer. The contrast in hydraulic conductivity and a difference in water levels are the bases for separating the Evangeline aquifer from the Chicot aquifer. The altitude of the base of the Evangeline aquifer is shown in figure 4. The Evangeline aquifer is the major source of ground water in the Houston district. In Galveston and southern Harris Counties, water in the Evangeline aquifer is saline and is not used.

Jasper Aquifer

The Jasper aquifer is composed of interbedded sand and clay layers consisting almost entirely of terrigenous clastic sediments. The approximate altitude of the top of the Jasper aquifer is shown in figure 5. Because the Jasper aquifer underlies shallower aquifers, withdrawals from the Jasper aquifer in terms of total withdrawals in Harris County are not significant. However, hydraulically it is capable of yields of as much as 3,000 gal/min to wells in adjacent Montgomery County (Baker, 1983). Only the upper part of the Jasper aquifer is utilized in Harris County.

DEVELOPMENT OF GROUND WATER

Several publications document the historical development of ground-water withdrawals in the Houston district (Wood and Gabrysch, 1965; Gabrysch, 1972, 1980, 1982; Jorgensen, 1975; Carr and others, 1985). The areas discussed in this report are Houston, Katy, Pasadena, Baytown-LaPorte, Johnson Space Center, Texas City, and Alta Loma (fig. 6).

Prior to 1977, ground water was the major source of freshwater available in the Houston district. Small quantities of surface water obtained from Lake Houston on the San Jacinto River had been available in parts of the Houston district since 1954. The city of Galveston began using surface water from Lake Houston in 1973. In late 1976, surface water from Lake Livingston on the Trinity River became available. The availability of the increased surface water caused ground-water production to decrease substantially in all areas of the Houston district except the Katy area.

In areas to the north, west, and southwest of the Houston area (fig. 6), ground-water withdrawals for public supply have steadily increased due to urban expansion and the lack of surface water. The average daily ground-water withdrawals for public supply, industrial use, and irrigation in the Houston district during 1975-84 are listed in tables 2-4.

In general, until 1977, water levels in wells in the Houston district were declining. However, during the last several years, Houston and several adjacent areas have been converting from ground water to surface water as the main water supply. With the increasing conversion from ground-water use to surface-water use, water levels in wells in the Chicot and Evangeline aquifers began to rise

REFERENCE 25


Geologic Atlas of Texas, Houston Sheet, 1:250,000. Bureau of Economic Geology, Austin, Texas, 1982.





COLSE SANCORORA DE CORORANA CON CONTRA CONTR

W. L. Being Miceser

FINDLOGIC ATLANS OF TREATAS FROM TON Sheet Seed 18250,000







EXPLANATION

Pleistocene

Miocene

QUATERNARY



Fill and spoil

Fill, F, material dredged for raising land surface above alluvium and barrier-island deposits and for creating land. Spoil, S, dredged material along waterways

Qal

Alluvium

Clay, silt, and sand, organic matter abundant locally, includes point-bar, natural levee, stream channel, backswamp, coastal marsh, mud-flat, and narrow beach deposits that are shown by line symbol


Holocene

late (?) Pleistocene



Barrier-island deposits

Sand, silt, and clay; mostly sand, well-sorted, fine-grained, abundant shells and shell fragments; interfingers with clay and silt in landward direction; includes beach ridge, spit, tidal channel, tidal-delta, and sand dune deposits



Deweyville Formation

Sand, silt, and clay, some gravel; includes point-lar, natural levee, stream channel, and backswamp deposits at a level only slightly above that of the persent floodplain; sand coarser than that in alluvium; surface characterized by relict meanders of much larger radius of curvature than those of present streams, some scattered pimple mounds; thickness locally more than 50 feet. High-level Deweyville, Qd?, surfaces cut into the Beaumont Formation, and high-level Deweyville deposits along Trinity River are intermediate in position between the surface of the Beaumont and the level of most Deweyville deposits



Beaumont Formation

Beaumont Formation, Qb, with barrier-island and beach deposits, Qbb, mapped separately. Beaumont Formation, Qb, mostly clay, silt, and sand, includes mainly stream channel, point-bar, natural levee, backswamp, and to a lesser extent coastal marsh and mud-flat deposits; concretions of calcium carbonate, irom oxide, and iron-manganese oxides in zone of weathering; surface almost featureless, characterized by relict river channels shown by meander natterns and pimple mounds on meanderbelt ridges, separated by areas of low, relatively smooth, featureless backswamp deposits without pimple mounds; thickness ± 100 feet. The stippled overprint (source shown in Index to Geologic Mapping) shows areas that are "Dominantly clay and mud of low permeability, high water-holding capacity, high compressibility, high to very high shrink-swell potential, poor drainage, level to depressed relief, low shear strength, and high plasticity; geologic units include interdistributary muds, abandoned channel-fill muds, and overbank fluvial muds." The nonstippled areas are "Dominantly clayey sand and silt of moderate permeability and drainage, low to moderate compressibility and shrink-swell potential, level relief with local mounds and ridges, and high shear strength; geologic units include meanderbelt, levee, creasse splay, and distributary sands"

15'

Barrier island and beach deposits, Qbb, mostly fine grained so slightly higher than that of surrounding deposits, character rounded depressions; probably part of "Ingleside" barrier Physical properties: "Dominantly sand, high to very high per compressibility, low shrink-swell potential, good drainage, strength, and low plasticity. Geologic units include beach, fitated flats, Pleistocene barrier and strandplain sands"



Lissie Formati

Upper part, clay, silt, sand, and very minor siliceous gravel abundant northwestward, locally calcareous, concretions manganese oxides common in zone of weathering; fluviatile. numerous rounded shallow depressions and pimple moun amount of gravel; gravel slightly coarser than in upper part, abundant than in upper part; fluviatile; very gently rolling.



Willis Formati

Clay, silt, sand, and minor siliceous gravel of granule to peb coarser than in younger units. Deeply weathered and later oxide locally, concretions of iron oxide numerous, noncalca



Tertiary rocks on Hockle

Sandstone, very fine grained, hard, abundant porcelaneou grayish white; possibly Catahoula Formation (Stenzel, reference.)

CR

Outcrop of caprock reported or Not found. Reportedly used for building

D

Fault

U. upthrown; D. downth.

10,000-meter Universal Transverse Merca

Partially funded by Texas Departme

4∩0000m.F

°00' 75-M3

REFERENCE 26

U.S. Environmental Protection Agency Hazard Ranking System Guidance Manual. EPA540-R-92-026. November 1992.


United States Environmental Protection Agency Office of Solid Waste and Emergency Response

Publication 9345.1-07 PB92-963377 EPA 540-R-92-026 November 1992

Superfund



Hazard Ranking System Guidance Manual



REFERENCE 27

Record of Communication To: John Cooper, Jacinto City Water Department From: Ken Jensen, Fluor Daniel, Inc., Regarding Jacinto City Water Supply, 5/22/95.

Date: Time: 22 May 95 2:20 pm PST

Call

From:

Ken Jensen

Entity/Position:

Fluor Daniel

Phone #:

(714) 975-2106

To:

John Cooper

Entity/Position:

Jacinto City Water Dept

Phone #:

(713) 674-8424

Relevant Information:

John called to provide information on the supply wells run by Jacinto City. These wells are slightly over 3 miles from the Wallisville Road site (East/Southeast).

Since 1992, Jacinto City has been required by regional ordinance (by the prompting of the Subsidence District people) to obtain 80% of its drinking water from surface water sources. The only surface water in the area is provided by the City of Houston, from its intakes on Lake Houston and the Trinity River.

Jacinto City supplies about 10,000 people with water; 20% of this water is derived from its groundwater wells located within 4 miles of the Wallisville Road site. Therefore, it is estimated that these wells supply water to approximately 2,000 people.

PRESCORE 3.0 - PRESCORE TCL File 07/25/94 NPL Characteristics Data Collection Form Olin, Wallsiville Road - 07/24/95

Record Information

- 1. Site Name: Olin, Wallsiville Road (as entered in CERCLIS)
- 2. Site CERCLIS Number: TXD000607028
- 3. Site Reviewer: Ken Jensen, Fluor Daniel, Inc.
- 4. Date: June 8, 1995
- 5. Site Location: Houston/Harris County, Texas (City/County, State)
- 6. Congressional District: 2
- 7. Site Coordinates: Single

Latitude: 29°47'20. "

Longitude: 95°17'20.

Site Description

- 1. Setting: Urban
- 2. Current Owner: Private Industrial
- 3. Current Site Status: Inactive
- 4. Years of Operation: Inactive Site, from and to dates: 1950 to 1972
- 5. How Initially Identified: State/Local Program
- 6. Entity Responsible for Waste Generation:
 - Other Pesticide Formulation
- 7. Site Activities/Waste Deposition:
 - Other Pesticide Formulation

Waste Description

8. Wastes Deposited or Detected Onsite:

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 NPL Characteristics Data Collection Form Olin, Wallsiville Road - 07/24/95

- Pesticides/Herbicides

Response Actions

- 9. Response/Removal Actions:
 - Emergency Waste Removal Has Occurred
 - Site Access Has Been Restricted
 - Other Removal Action Has Occurred

RCRA Information

- 10. For All Active Facilities, RCRA Site Status:
 - Not Applicable

Demographic Information

- 11. Workers Present Onsite: Yes
- 12. Distance to Nearest Non-Worker Individual: > 10 Feet 1/4 Mile
- 13. Residential Population Within 1 Mile: 7762.0
- 14. Residential Population Within 4 Miles: 156465.0

Water Use Information

- 15. Local Drinking Water Supply Source:
 - Ground Water (within 4 mile distance limit)
- 16. Total Population Served by Local Drinking Water Supply Source: 20706.0
- 17. Drinking Water Supply System Type for Local Drinking Water Supply Sources:
 - Municipal (Services over 25 People)
 - Private
- 18. Surface Water Adjacent to/Draining Site:

PAGE: 2

PAGE:

1

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 HRS DOCUMENTATION RECORD Olin, Wallsiville Road - 07/24/95

1. Site Name: Olin, Wallsiville Road (as entered in CERCLIS)

2. Site CERCLIS Number: TXD000607028

3. Site Reviewer: Ken Jensen, Fluor Daniel, Inc.

4. Date: June 8, 1995

5. Site Location: Houston/Harris County, Texas (City/County, State)

6. Congressional District: 2

7. Site Coordinates: Single

Latitude: 29°47'20. " Longitude: 95°17'20.

	Score
Ground Water Migration Pathway Score (Sgw)	0.38
Surface Water Migration Pathway Score (Ssw)	0.00
Soil Exposure Pathway Score (Ss)	16.48
Air Migration Pathway Score (Sa)	1.44

Site Score	8.28	
	<u> </u>	

NOTE

EPA uses the terms "facility," "site," and "release" interchangeably. The term "facility" is broadly defined in CERCLA to include any area where hazardous substances have "come to be located" (CERCLA Section 109(9)), and the listing process is not intended to define or reflect boundaries of such facilities or releases. Site names, and references to specific parcels or properties, are provided for general identification purposes only. Knowledge regarding the extent of sites will be refined as more information is developed during the RI/FS and even during implementation of the remedy.

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 2

WASTE QUANTITY
Olin, Wallsiville Road - 07/24/95

1. WASTESTREAM QUANTITY SUMMARY TABLE, SOURCE: Soils on site

a. Wastestream ID	
b. Hazardous Constituent Quantity (C) (lbs.)	0.00
c. Data Complete?	NO
d. Hazardous Wastestream Quantity (W) (lbs.)	0.00
e. Data Complete?	NO
f. Wastestream Quantity Value (W/5,000)	0.00E+00

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 3

WASTE QUANTITY

Olin, Wallsiville Road - 07/24/95

2. SOURCE HAZARDOUS WASTE QUANTITY FACTOR TABLE

a.	Source ID		Soils on site	
b.	Source Type		Contaminated Soi	1
c.	Secondary Source Type		N.A.	
d.	Source Vol.(yd3/gal)	Source Area (ft2)	0.00	784080.00
e.	Source Volume/Area Va	lue	2.31E+01	
f.	Source Hazardous Cons (HCQ) Value (sum of 1	***	0.00E+00	
g.	Data Complete?		NO	
h.	Source Hazardous Wast (WSQ) Value (sum of 1		0.00E+00	
i.	Data Complete?		NO	
k.	Source Hazardous Wast Value (2e, 2f, or 2h)	e Quantity (HWQ)	2.31E+01	

Source Hazardous Substances	Depth (feet)	Liquid	Concent.	Units
DDD	< 2	NO	1.0E+02	ppm
DDE	< 2	NO	1.0E+02	ppm
DDT	< 2	NO	1.0E+02	mqq
Lindane	< 2	NO	1.0E+02	ppm
Pentachloronitrobenzene	< 2	NO	1.0E+02	mqq
Toxaphene	< 2	NO	1.0E+03	ppm

Documentation for Source Type:

Main constituent of concern on site is contaminated soils (Ref 03, p. 6).

Reference: 3

PAGE:

Olin, Wallsiville Road - 07/24/95

Documentation for Source Hazardous Substances:

Based on conversations with TNRCC field sampling personnel, there are 6 major contaminants on site: lindane, pentachloronitrobenzene, 4,4'-DDT; 4,4'-DDD; 4,4'-DDE, and toxaphene (Ref 12, 001). This is echoed by the EPA Potential Hazardous Waste Site inspection Report (Ref 03, p. 3)

Reference: 3, 12

Documentation for Source Area:

The entire 18 acre site was considered as contaminated for scoring purposes. Square footage was calculated by multiplying the 18 acres by 43,560 square feet per acre (Ref 03, 003).

Reference: 3

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 5 WASTE QUANTITY Olin, Wallsiville Road - 07/24/95

3. SITE HAZARDOUS WASTE QUANTITY SUMMARY

No. Source ID	_	Vol. or Area Value (2e)	Constituent or Wastestream Value (2f,2h)	Hazardous Waste Qty. Value (2k)
1 Soils on site	GW-SE-A	2.31E+01	0.00E+00	2.31E+01

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 6 WASTE QUANTITY

Olin, Wallsiville Road - 07/24/95

4. PATHWAY HAZARDOUS WASTE QUANTITY AND WASTE CHARACTERISTICS SUMMARY TABLE

Migration Pathway	Contaminant Value	HWQVs*	WCVs**	
Ground Water	Toxicity/Mobility	2.00E-01	10	1
SW: Overland Flow, DW	Tox./Persistence	0.00E+00	0	0
SW: Overland Flow, HFC	Tox./Persis./Bioacc.	0.00E+00	0	0
SW: Overland Flow, Env	Etox./Persis./Bioacc.	0.00E+00	0	0
SW: GW to SW, DW	Tox./Persistence	2.00E-01	10	1
SW: GW to SW, HFC	Tox./Persis./Bioacc.	1.00E+03	10	10
SW: GW to SW, Env	Etox./Persis./Bioacc.	1.00E+04	10	18
Soil Exposure:Resident	Toxicity	1.00E+04	10	18
Soil Exposure: Nearby	Toxicity	1.00E+04	10	18
Air	Toxicity/Mobility	2.00E+02	10	6

^{*} Hazardous Waste Quantity Factor Values

Note:

SW = Surface Water

GW = Ground Water

DW = Drinking Water Threat HFC = Human Food Chain Threat Env = Environmental Threat

^{**} Waste Characteristics Factor Category Values

PAGE:

3

- Stream

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 GROUND WATER MIGRATION PATHWAY SCORESHEET Olin, Wallsiville Road - 07/24/95

GROUND WATER MIGRATION PATHWAY Factor Categories & Factors	Maximum Value	Value Assigned
Likelihood of Release to an Aquifer Aquifer: Evangeline aquifer		•
 Observed Release Potential to Release Containment Net Precipitation Depth to Aquifer Travel Time Potential to Release [lines 2a(2b+2c+2d)] Likelihood of Release 	550 10 10 5 35 500 550	0 10 3 1 5 90 230
Waste Characteristics		
4. Toxicity/Mobility 5. Hazardous Waste Quantity 6. Waste Characteristics	* * 100	2.00E-01 10 1
Targets	·	
7. Nearest Well 8. Population 8a. Level I Concentrations 8b. Level II Concentrations 8c. Potential Contamination 8d. Population (lines 8a+8b+8c) 9. Resources 10. Wellhead Protection Area 11. Targets (lines 7+8d+9+10) 12. Targets (including overlaying aquifers) 13. Aquifer Score	50 ** ** ** 5 20 ** ** 100	2.00E+00 0.00E+00 0.00E+00 1.31E+02 1.31E+02 0.00E+00 0.00E+00 1.33E+02 1.38E+02 0.38
GROUND WATER MIGRATION PATHWAY SCORE (Sgw)	100	0.38

^{*} Maximum value applies to waste characteristics category.
** Maximum value not applicable.

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 GROUND WATER PATHWAY AQUIFER SUMMARY

Olin, Wallsiville Road - 07/24/95

No. Aquifer ID	Туре	Overlaying No.	Inter- Connected with	Likelihood of Release	Targets
1 Chicot Aquifer	Non K	0	0	230	2.00E+01
2 Evangeline aquifer	Non K	1	1	230	1.38E+02

Containment

No.	Source ID	HWQ Value	Containment	Value
1	Soils on site	2.31E+01	10	
===:		 inment Factor	======================================	:====

Documentation for Ground Water Containment, Source Soils on site:

Reference 9, Table 3-2. Evidence of hazardous substance migration from the area, and no liner.

Reference: 9

Net Precipitation

Net Precipitation (inches)

N.A.

Documentation for Net Precipitation:

HRS Figure 3-2 was used to determine a net precipitation factor of 3 (Ref 9, figure 3-2).

Reference: 9

PAGE: 2

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Chicot Aquifer Olin, Wallsiville Road - 07/24/95

PAGE: AOUIFER 3

Aguifer: Chicot Aguifer

Type of Aquifer: Non Karst

Overlaying Aquifer: 0

Interconnected with: 0

Documentation for Chicot Aquifer Aquifer:

The site is underlain by the Pleistocene Beaumont Formation (thickness 100+ ft.) which in turn is underlain by the Montgomery Formation (approximate thickness of 100+ ft. beneath site). Both units are composed of fluvial deltaic deposits of alternating clay, silt, sand and gravel beds, and are considered the two upper units of the Chicot Aquifer (Ref. 06, 002; Ref.25,002-003).

Reference: 6,25

OBSERVED RELEASE

No. Well ID

Well Type

Distance

Level of Contamination (miles)

- N/A and/or data not specified

Observed Release Factor

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94
GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Chicot Aquifer
Olin, Wallsiville Road - 07/24/95

PAGE: AQUIFER 4

POTENTIAL TO RELEASE

Containment

Containment Factor

10

Net Precipitation

Net Precipitation Factor

3

Depth to Aquifer

A. Depth of Hazardous Substances

3.00

feet

Documentation for Depth of Hazardous Substances:

Depth of contamination has not been established at the site. S ampling data exhibited contamination within the upper three feet of surface soils (Ref.9,003; Ref.11), therefore a depth of three feet was assigned.

Reference: 9,11

B. Depth to Aquifer from Surface

20.00

feet

Documentation for Depth to Aquifer from Surface :

As Per EPA Site Inspection Report (Ref 03, 008).

Reference: 3

C. Depth to Aquifer (B - A)

17.00

feet

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94
GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Chicot Aquifer
Olin, Wallsiville Road - 07/24/95

PAGE: AQUIFER

Depth to Aquifer Factor

5

Travel Time

Are All Layers Karst?

NO

Thickness of Layer(s) with Lowest Conductivity

20.00

feet .

Documentation for Thickness of Layers with Lowest Conductivity:

Subsurface of this site has not been characterized, although historic reports on the subsurface of the general area within which the site lies indicate that it may be highly variable. As stated within file references, "Because the subsurface geology is highly variable, it is very difficult to determine the configuration of subsurface soils in the proximity of the site. In order to determine the local subsurface soil structure, site specific investigation is necessary." (Ref. 13, Attachment C, 001). However, the primary constituents of the surface soils located beneath the site is clay and mud of low permeability (Ref.25). Therefore, the surface soils (to the depth of the aquifer) were determined to have the lowest conductivity (depth of 20 feet).

Reference: 13,25

Hydraulic Conductivity (cm/sec)

1.0E-07

Documentation for Hydraulic Conductivity:

As per EPA Site Inspection Report (Ref 03, 009)

Reference: 3

Travel Time Factor

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE:
GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Chicot Aquifer
Olin, Wallsiville Road - 07/24/95

6

Potential to Release Factor 230

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE:
GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Evangeline aquifer AQUIFER
Olin, Wallsiville Road - 07/24/95

Aquifer: Evangeline aquifer

Type of Aquifer: Non Karst

Overlaying Aquifer: 1

Interconnected with: 1

Documentation for Evangeline aquifer Aquifer:

The Evangeline aquifer is geologically similar to the Chicot aquifer-consisting of fluvial deltaic deposits of alternating layers of clays, silts, sands, and gravels. The Chicot and the Evangeline are considered an undifferentiated coastal aquifer, delineated only by the Evangeline's smaller hydraulic conductivity (Ref. 23-002; Ref. 24,002-004)

Reference: 23,24

OBSERVED RELEASE

No. Well ID Well Type Distance (miles) Level of Contamination

- N/A and/or data not specified

Observed Release Factor

0

7

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE:
GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Evangeline aquifer AQUIFER
Olin, Wallsiville Road - 07/24/95

POTENTIAL TO RELEASE

Containment

Containment Factor 10

Net Precipitation

Net Precipitation Factor 3

Depth to Aquifer

A. Depth of Hazardous Substances 3.00 feet

Documentation for Depth of Hazardous Substances:

The depth of contamination was not stated within the file information. However, sampling data exhibited contamination within the upper 3 feet of the surface soils (Ref.9-003-004; Ref.11), therefore, a depth of 3 feet was assigned.

Reference: 9,11

B. Depth to Aquifer from Surface

800.00 feet

8

Documentation for Depth to Aquifer from Surface :

The depth to the Evangeline aquifer was determined through interpretation of hydrologic unit cross-sections (Ref.24-)

Reference: 24

PRESCORE 3.0 - PRESCORE.TCL File 07/25/		PAGE:	9
GROUND WATER PATHWAY LIKELIHOOD OF RELEASE Evangeline Olin, Wallsiville Road - 07/24/95	aquiter	AQUITER	
C. Depth to Aquifer (B - A)	797.00	feet	
Depth to Aquifer Factor	1		
Travel Time			
Are All Layers Karst?	NO		
Thickness of Layer(s) with Lowest Conductivity	0.00	feet	
• , ,			
Hydraulic Conductivity (cm/sec)	0.0E-00		
Turner 1 Time To the co	_		
Travel Time Factor	5		
Potential to Release Factor	90	======	====

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 GROUND WATER PATHWAY WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

Source: 1 Soils on site

Source Hazardous Waste Quantity Value: 23.06

Hazardous Substance	Toxicity Value	Mobility Value	Toxicity/ Mobility Value	
DDD	100	2.00E-07	2.00E-05	
DDE	100	2.00E-07	2.00E-05	
DDT	1000	2.00E-07	2.00E-04	
Lindane	10000	2.00E-05	2.00E-01	
Pentachloronitrobenzene	1000	2.00E-05	2.00E-02	
Toxaphene	1000	2.00E-05	2.00E-02	

PAGE: 10

PREscore 3.0 - PRESCORE.TCL File 07/25/94 GROUND WATER PATHWAY WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

PAGE:

Hazardous Substances Found in an Observed Release

Well Observed Release Hazardous Substance No.

Toxicity Value

Mobility Value

Toxicity/ Mobility

11

Value

⁻ N/A and/or data not specified

Toxicity/Mobility Value from Source Hazardous Substances:	2.00E-01
Toxicity/Mobility Value from Observed Release Hazardous Substances:	0.00E+00
Toxicity/Mobility Factor:	2.00E-01
Sum of Source Hazardous Waste Quantity Values:	2.31E+01
Hazardous Waste Quantity Factor:	10
Waste Characteristics Factor Category:	1

PREscore 3.0 - PRESCORE.TCL File 07/25/94

GROUND WATER PATHWAY WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

PAGE:

12

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 13 GROUND WATER PATHWAY TARGETS FOR AQUIFER Chicot Aquifer Olin, Wallsiville Road - 07/24/95

Population by Well

			Distance	Level of	
No.	Well ID	Sample Type	(miles)	Contamination	Population

- N/A and/or data not specified

Level I Population Factor: 0.00

Level II Population Factor: 0.00

Q

14

Potential Contamination by Distance Category

Distance Category (miles)	Population	Value	
> 0 to 1/4	0.0	0.00E+00	
> 1/4 to 1/2	0.0	0.00E+00	
> 1/2 to 1	0.0	0.00E+00	
> 1 to 2	0.0	0.00E+00	
> 2 to 3	0.0	0.00E+00	
> 3 to 4	2000.0	1.31E+01	

Potential Contamination Factor:

13.000

Documentation for Target Population > 3 to 4 miles Distance Category:

Jacinto City has three drinking water wells drawing from the Chicot aquifer within the 3-4 mile radius of the site (Ref.18,001-004). Ground water supplies 20% of the total drinking water resources. The other 80% is supplied by City of Houston surface water sources. A total population of 10,000 is served by these wells (Ref.16). Overall attribution of ground water is detailed below:

(10,000 people) (.2) = 2,000 people served.

Reference: 16,18

Nearest Well

Level of Contamination: Potential

Distance in miles: 3.20

Nearest Well Factor: 2.00E+00

PREscore 3.0 - PRESCORE.TCL File 07/25/94 GROUND WATER PATHWAY TARGETS FOR AQUIFER Chicot Aquifer

Olin, Wallsiville Road - 07/24/95

PAGE:

15

Documentation for Nearest Well:

Distance of 3.2 miles to the nearest drinking water well, the Jacinto City well (municipal supply). The distance was obtained by plotting well positions onto the USGS map for the site area and measuring the distance from the site to the wells. This was verified by comparing distances to the Harris/Galveston Coastal Subsidence District database information which included radial distance from the site to the listed wells (Ref. 07, 001)

Reference: 7

Resources

Resource Use: YES

Resource Factor: 5.00E+00

Documentation for Resources:

Ground water is used in formulation of vinegar on a commercial scale, therefore ground water has a use as a resource. The well is approximately 3.5 miles from the site (Ref. 7,003; Ref.10)

Reference: 10,7

Wellhead Protection Area

No wellhead protection area

Wellhead Protection Area Factor: 0.00E+00

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 16
GROUND WATER PATHWAY TARGETS FOR AQUIFER Chicot Aquifer
Olin, Wallsiville Road - 07/24/95

Documentation for Wellhead Protection Area:

TNRCC personnel confirmed that a wellhead protection area does not exist within 4 miles of the site (Ref. 11,001).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 17 GROUND WATER PATHWAY TARGETS FOR AQUIFER Evangeline aquifer Olin, Wallsiville Road - 07/24/95

Population by Well

No. Well ID Sample Type Distance Level of (miles) Contamination Population

- N/A and/or data not specified

Level I Population Factor:

0.00

Level II Population Factor:

0.00

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: GROUND WATER PATHWAY TARGETS FOR AQUIFER Evangeline aquifer Olin, Wallsiville Road - 07/24/95

Potential Contamination by Distance Category

Distance Category (miles)	Population	Value	
> 0 to 1/4	0.0	0.00E+00	
> 1/4 to 1/2	0.0	0.00E+00	
> 1/2 to 1	0.0	0.00E+00	
> 1 to 2	0.0	0.00E+00	
> 2 to 3	0.0	0.00E+00	
> 3 to 4	18695.0	1.31E+02	

Potential Contamination Factor:

131.000

Documentation for Target Population > 3 to 4 miles Distance Category:

There are three City of Houston wells located within the 3-4 mile radius of the site. These wells draw water from the Evangeline aquifer at an average depth of 1500 feet. Each well serves an approximate population of 6,232; three wells an average of 18,695 people (Ref.21, 001).

Reference: 21

Nearest Well

Level of Contamination: Potential

Distance in miles: 3.30

Nearest Well Factor: 2.00E+00

Documentation for Nearest Well:

The nearest well drawing water from the Evangeline aquifer is identified as a City of Houston water well (well #1), and is located approximately 3.3 miles from the site, at a depth of 1993 feet (Ref 15,001-004).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 19 GROUND WATER PATHWAY TARGETS FOR AQUIFER Evangeline aquifer Olin, Wallsiville Road - 07/24/95

Reference: 15

Resources

Resource Use: NO

Resource Factor: 0.00E+00

Documentation for Resources:

No resources identified (Ref 7,001-004).

Reference: 7

Wellhead Protection Area

No wellhead protection area

Wellhead Protection Area Factor: 0.00E+00

Documentation for Wellhead Protection Area:

TNRCC personnel have verified that no wellhead protection area exists within a 4-mile radius of the site (Ref.11,001).

PREscore 3.0 - PRESCORE.TCL File 07/25/94 SOIL EXPOSURE PATHWAY SCORESHEET Olin, Wallsiville Road - 07/24/95

SOIL EXPOSURE PATHWAY Factor Categories & Factors RESIDENT POPULATION THREAT	Maximum Value	Value Assigned
Likelihood of Exposure		
1. Likelihood of Exposure	550	550
Waste Characteristics		
2. Toxicity 3. Hazardous Waste Quantity 4. Waste Characteristics	* * 100	1.00E+04 10 18
Targets		
5. Resident Individual 6. Resident Population	50	5.00E+01
6a. Level I Concentrations 6b. Level II Concentrations 6c. Resident Population (lines 6a+6b)	** ** **	8.20E+01 0.00E+00 8.20E+01
7. Workers 8. Resources 9. Terrestrial Sensitive Environments	15 5 ***	5.00E+00 0.00E+00 0.00E+00
10. Targets (lines 5+6c+7+8+9)	**	1.37E+02
11. RESIDENT POPULATION THREAT SCORE	**	1.36E+06

^{*} Maximum value applies to waste characteristics category.
** Maximum value not applicable.
*** No specific maximum value applies, see HRS for details.

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 SOIL EXPOSURE PATHWAY SCORESHEET Olin, Wallsiville Road - 07/24/95

SOIL EXPOSURE PATHWAY Factor Categories & Factors NEARBY POPULATION THREAT	Maximum Value	Value Assigned
Likelihood of Exposure		:
12. Attractiveness/Accessibility 13. Area of Contamination 14. Likelihood of Exposure	100 100 500	l
Waste Characteristics		
15. Toxicity 16. Hazardous Waste Quantity 17. Waste Characteristics	* * 100	1.00E+04 10 18
Targets		
18. Nearby Individual 19. Population Within 1 Mile 20. Targets (lines 18+19)	1 ** **	0.00E+00 4.00E+00 4.00E+00
21. NEARBY POPULATION THREAT SCORE	**	3.60E+03
SOIL EXPOSURE PATHWAY SCORE (Ss)	100	16.48

^{*} Maximum value applies to waste characteristics category.
** Maximum value not applicable.

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 3
SOIL EXPOSURE PATHWAY RESIDENT POPULATION THREAT LIKELIHOOD OF EXPOSURE
Olin, Wallsiville Road - 07/24/95

Likelihood of Exposure

No.	Source ID	Level	of	Contamination
1	Soils on site			Level I

Likelihood of Exposure Factor: 550

Documentation for Area of Contamination, Source Soils on site:

Conservative estimate based on entire site acreage (18 acres) multiplyed by 43,560 square feet per acre (Ref.3,003).

Reference: 3

Source Hazardous Substance No.		Depth Concent. (ft.)		Cancer	RFD	Units	
1	DDD	< 2	1.0E+02	2.4E+00	0.0E+00	ppm	
1	DDE	< 2	1.0E+02	1.7E+00	0.0E+00	ppm	
1	DDT	< 2	1.0E+02	1.7E+00	2.9E+02	ppm	
1	Lindane	< 2	1.0E+02	4.5E-01	1.7E+02	ppm	
1	Pentachloronitrobenzene	< 2	1.0E+02	2.2E+00	1.7E+03	ppm	
1	Toxaphene	< 2	1.0E+03	5.3E-01	0.0E+00	ppm	

Documentation for Source Soils on site, Contaminants:

Based on conversations with TNRCC field sampling personnel, there are 6 major contaminants on site: lindane, pentachloronitrobenzene, 4,4'-DDT; 4,4'-DDD; 4,4'-DDE, and toxaphene (Ref 12, 001). This is echoed by the EPA Potential Hazardous Waste Site inspection Report (Ref 03, p. 3)

Reference: 3, 12

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE:
SOIL EXPOSURE PATHWAY RESIDENT POPULATION THREAT WASTE CHARACTERISTICS
Olin, Wallsiville Road - 07/24/95

Source: 1 Soils on site

Source Hazardous Waste Quantity Value: 23.06

Hazardous Substance	Toxicity Value		
DDD	100		
DDE	100		
DDT	1000		
Lindane	10000	·	
Pentachloronitrobenzene	1000		
Toxaphene	1000		

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 501L EXPOSURE PATHWAY RESIDENT POPULATION THREAT WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

Toxicity Factor:	1.00E+04
Sum of Source Hazardous Waste Quantity Values:	2.31E+01
Hazardous Waste Quantity Factor:	10
Waste Characteristics Factor Category.	1.8

PREscore 3.0 - PRESCORE.TCL File 07/25/94 PAGE: SOIL EXPOSURE PATHWAY RESIDENT POPULATION THREAT TARGETS

Olin, Wallsiville Road - 07/24/95

Targets

Level I Population: 8.2

Value: 82.00

6

Documentation for Level I Population:

Historic sampling has confirmed that at least one resident located adjacent to the site has toxaphene contamination (up to 156 ppm) within the soils (Ref.17,005). The number of residents possibly affected by the soil contamination was determined through topographic interpretation (house count). There are three residences located along the northern site boundary. Each residence is estimated to house an average population of 2.72 (Ref.22,002). Therefore it is estimated that 8.2 people may be affected by source contaminants. No schools or daycare centers are located within 200 feet of an area of observed contamination (Ref.20).

Reference: 17,22,20

Level II Population: 0.0 Value: 0.00

Workers:

50.0

Value: 5.00

Documentation for Workers:

The site does not support any commercial enterprise; however, there are some workers on the property of Mustang equipment, which lies adjacent to the site and therefore may be considered "within 200 ft." of the site (Ref.03,003).

Reference: 3

Resident Individual:

Level I

Value: 50.00

Resources:

ИО

Value: 0.00

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: SOIL EXPOSURE PATHWAY RESIDENT POPULATION THREAT TARGETS
Olin, Wallsiville Road - 07/24/95

Documentation for Resources:

No resources identified Ref.9).

Reference: 9

Terrestial Sensitive Environment

Value

7

- N/A and/or data not specified

Terrestrial Sensitive Environments Factor: 0.00

Likelihood of Exposure

No.	Source ID	Level of Contamination	Attractiveness/ Accessibility	Area of Contam. (sq. feet)
1	Soils on site	Level I	5	784080
Sum		ess/Accessibility as Of Contamination on Value: 100		784080

Likelihood of Exposure Factor Category: 50

Documentation for Attractiveness/Accessibility, Source Soils on site:

The site is currently fenced and located adjacent to an area of residential development; as well, it borders a railroad and a rail yard (Ref. 09, table 5-6).

Reference: 9

Sourc	e Hazardous Substance	Depth (ft.)	Concent.	Cancer	RFD	Units
1	DDD	< 2	1.0E+02	2.4E+00	0.0E+00	ppm
1	DDE	< 2	1.0E+02	1.7E+00	0.0E+00	mqq
1	DDT	< 2	1.0E+02	1.7E+00	2.9E+02	ppm
1	Lindane	< 2	1.0E+02	4.5E-01	1.7E+02	ppm
1	Pentachloronitrobenzene	< 2	1.0E+02	2.2E+00	1.7E+03	ppm
1	Toxaphene	< 2	1.0E+03	5.3E-01	0.0E+00	ppm

Documentation for Source Soils on site, Contaminants:

Based on conversations with TNRCC field sampling personnel, there are 6 major contaminants on site: lindane, pentachloronitrobenzene, 4,4'-DDT; 4,4'-DDD; 4,4'-DDE, and toxaphene (Ref 12, 001). This is echoed by the EPA Potential Hazardous Waste Site inspection Report (Ref 03, p. 3)

Reference: 3, 12

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: SOIL EXPOSURE PATHWAY NEARBY POPULATION THREAT WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

Source: 1 Soils on site

Source Hazardous Waste Quantity Value: 23.06

Hazardous Substance	Toxicity Value	
DDD	100	
DDE	100	
DDT	1000	
Lindane	10000	
Pentachloronitrobenzene	1000	
Toxaphene	1000	

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 10 SOIL EXPOSURE PATHWAY NEARBY POPULATION THREAT WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

Toxicity Factor:	1.00E+04
Sum of Source Hazardous Waste Quantity Values:	2.31E+01
Hazardous Waste Quantity Factor:	10
Waste Characteristics Factor Category:	18

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 11 SOIL EXPOSURE PATHWAY NEARBY POPULATION THREAT TARGETS Olin, Wallsiville Road - 07/24/95

Nearby Individual

Population within 1/4 mile: 174.0

Nearby Individual Value: 0.0

Population Within 1 Mile

Travel Distance Category	Number of People	Value	
> 0 to 1/4 mile	174.0	0.4	
> 1/4 to 1/2 mile	0.0	0.0	
> 1/2 to 1 mile	7588.0	3.3	

Population Within 1 Mile Factor: 4.0

Documentation for Population > 0 to 1/4 mile Distance Category:

U.S. Environmental Protection Agency, Geographical Exposure Modeling System (GEMS) Database, compiled from the U.S. Census Bureau 1990 data, accessed 3/27/95 (Ref 05, 002).

Reference: 5

Documentation for Population > 1/4 to 1/2 mile Distance Category:

No population in this distance limit according to data derived from U.S. EPA GEMS database (Ref. 05, 002).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE:
SOIL EXPOSURE PATHWAY NEARBY POPULATION THREAT TARGETS
Olin, Wallsiville Road - 07/24/95

Documentation for Population > 1/2 to 1 mile Distance Category:

There are 7588 people living in this taget limit according to data derived from U.S. EPA GEMS database (Ref. 05, 002).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: AIR PATHWAY SCORESHEET Olin, Wallsiville Road - 07/24/95

AIR MIGRATION PATHWAY Factor Categories & Factors	Maximum Value	Value Assigned
Likelihood of Release		
1. Observed Release 2. Potential to Release 2a. Gas Potential to Release 2b. Particulate Potential to Release 2c. Potential to Release 3. Likelihood of Release	550 500 500 500 550	300 330 330 330
Waste Characteristics		
4. Toxicity/Mobility 5. Hazardous Waste Quantity 6. Waste Characteristics	* * 100	2.00E+02 10 6
Targets		
7. Nearest Individual 8. Population 8a. Level I Concentrations 8b. Level II Concentrations 8c. Potential Contamination 8d. Population (lines 8a+8b+8c) 9. Resources 10. Sensitive Environments 10a. Actual Contamination 10b. Potential Contamination 10c. Sens. Environments(lines 10a+10b) 11. Targets (lines 7+8d+9+10c)	50 ** ** ** 5 *** ***	2.00E+01 0.00E+00 0.00E+00 4.00E+01 4.00E+01 0.00E+00 0.00E+00 0.00E+00 6.00E+01
AIR MIGRATION PATHWAY SCORE (Sa)	100	1.44E+00

^{*} Maximum value applies to waste characteristics category.
** Maximum value not applicable.
*** No specific maximum value applies, see HRS for details.

PREscore 3.0 - PRESCORE.TCL File 07/25/94 AIR PATHWAY LIKELIHOOD OF RELEASE Olin, Wallsiville Road - 07/24/95

PAGE: 2

OBSERVED RELEASE

No. Sample ID	Distance (miles)	Level of	Contamination	
- N/A and/or data not	specified			
=======================================	=======================================	========	=======================================	========

Observed Release Factor: 0

PREscore 3.0 - PRESCORE.TCL File 07/25/94 AIR PATHWAY LIKELIHOOD OF RELEASE

Olin, Wallsiville Road - 07/24/95

Gas Migration Potential

GAS POTENTIAL TO RELEASE

		Gas Contain		Gas Migrtn Potent		Gas Potential to Rel.
Source ID	Source Type	Value (A)	Value (B)	Value (C)	Sum (B+C)	Value A(B+C)
Soils on site	Contaminated Soil	10	19	11	30	300

Gas Potential to Release Factor:

300

Documentation for Gas Containment, Source Soils on site:

Source contains less than 1 ft. of clean cover and is not heavily vegetated (Ref 9, table 6-3).

Reference: 9

Documentation for Source Type, Source Soils on site:

Main constituent of concern on site is contaminated soils (Ref 03, p. 6).

Reference: 3

PAGE: 3 PRESCORE 3.0 - PRESCORE.TCL File 07/25/94
AIR PATHWAY LIKELIHOOD OF RELEASE

Olin, Wallsiville Road - 07/24/95

Source: Soils on site

Gaseous Hazardous Substance	Hazardous Substance Gas Migration Potential Value
DDD	6
DDE	6
DDT	6
Lindane	11
Pentachloronitrobenzene	11
Toxaphene	6

Average of Gas Migration Potential Value for 3 Hazardous Substances: 9.333

Gas Migration Potential Value From Table 6-7: 11

PAGE: 4

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 AIR PATHWAY LIKELIHOOD OF RELEASE Olin, Wallsiville Road - 07/24/95

Particulate Migration Potential

PARTICULATE POTENTIAL TO RELEASE

Source ID	Source Type	Partic. Contain Value (A)	Source	Potent	Sum	Partic. Potential to Rel. Value A(B+C)
Soils on site	Contaminated Soil	10	22	11	33	330

Particulate Potential to Release Factor:

Documentation for Particulate Containment, Source Soils on site:

Source area contains less than 1 ft. of clean cover and is not heavily vegetated (Ref 09, table 6-9).

Reference: 9

Documentation for Source Type, Source Soils on site:

Main constituent of concern on site is contaminated soils (Ref 03, p. 6).

Reference: 3

PAGE: 5

330

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94
AIR PATHWAY LIKELIHOOD OF RELEASE
Olin, Wallsiville Road - 07/24/95

Documentation for Particulate Migration Potential:

Figure 6-2 used to determine a particulate migration potential factor of 11 (Ref 01, figure 6-2).

Reference: 1

PAGE: 6

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 7 AIR PATHWAY LIKELIHOOD OF RELEASE Olin, Wallsiville Road - 07/24/95

Source: Soils on site

Particulate Hazardous Substance

DDD

DDE

DDT

Lindane

Pentachloronitrobenzene

Toxaphene

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 AIR PATHWAY WASTE CHARACTERISTICS Olin, Wallsiville Road - 07/24/95

Source: 1 Soils on site

Source Hazardous Waste Quantity Value: 23.06

Hazardous Substance	Toxicity Value	Gas Mobility Value	Particulate Mobility Value	Toxicity/ Mobility Value
DDD	100	2.00E-03	8.00E-04	2.00E-01
DDE	100	2.00E-03	8.00E-04	2.00E-01
DDT	1000	2.00E-03	8.00E-04	2.00E+00
Lindane	10000	2.00E-02	8.00E-04	2.00E+02
Pentachloronitrobenzene	1000	2.00E-02	8.00E-04	2.00E+01
Toxaphene	1000	2.00E-03	8.00E-04	2.00E+00

PAGE: 8

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 AIR PATHWAY WASTE CHARACTERISTICS

Olin, Wallsiville Road - 07/24/95

Hazardous Substances Found in an Observed Release

Sample Observed Release ID Hazardous Substance

Particulate Toxicity/

Mobility Value

Gas

Toxicity/

Mobility Value

PAGE:

9

- N/A and/or data not specified

Documentation for Particulate Mobility:

Figure 6-3 was used to determine a particulate mobility factor of .0008 (Ref 01, figure 6-3).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 10
AIR PATHWAY WASTE CHARACTERISTICS
Olin, Wallsiville Road - 07/24/95

Toxicity/Mobility Value from Source Hazardous Substances:	2.00E+02
Toxicity/Mobility Value from Observed Release Hazardous Substances:	0.00E+00
Toxicity/Mobility Factor:	2.00E+02
Sum of Source Hazardous Waste Quantity Values:	2.31E+01
Hazardous Waste Quantity Factor:	10
Waste Characteristics Factor Category:	6

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: AIR PATHWAY TARGETS

Olin, Wallsiville Road - 07/24/95

Actual Contamination

Distance

No. Sample ID (miles)

Level of Contamination

11

Potential Contamination

Distance Categories Subject to Potential Contamination	Population	Value	
Onsite	0.0	0.0000	
> 0 to 1/4 mile	174.0	4.1000	
> 1/4 to 1/2 mile	0.0	0.0000	
> 1/2 to 1 mile	7588.0	8.3000	
> 1 to 2 miles	25074.0	8.3000	
> 2 to 3 miles	38483.0	12.0000	
> 3 to 4 miles	85146.0	7.3000	

Potential Contaminantion Factor: 40.0000

Documentation for Population Onsite Distance Category:

Conversation with current TNRCC project manager regarding current onsite conditions (Ref 01, 001).

Reference: 1

Documentation for Population > 0 to 1/4 mile Distance Category:

U.S. EPA GEMS population database, (Ref 20, 002-003).

⁻ N/A and/or data not specified

PAGE:

12

Documentation for Population > 1/4 to 1/2 mile Distance Category:

U.S. EPA GEMS population database (Ref 20, 002-003).

Reference: 20

Documentation for Population > 1/2 to 1 mile Distance Category:

U.S. EPA GEMS population database, (Ref 20, 002-003).

Reference: 20

Documentation for Population > 1 to 2 miles Distance Category:

U.S. EPA GEMS population database (Ref 20, 002-003).

Reference: 20

Documentation for Population > 2 to 3 miles Distance Category:

U.S. EPA GEMS population database (Ref 20, 002-003).

Reference: 20

Documentation for Population > 3 to 4 miles Distance Category:

U.S. EPA GEMS population database (Ref. 20, 002-003).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 AIR PATHWAY TARGETS

PAGE:

13

Olin, Wallsiville Road - 07/24/95

Nearest Individual Factor

Level of Contamination: Potential

Distance in miles: 0 to 1/8

Nearest Individual Value: 20

Documentation for Nearest Individual:

Site-related contamination (toxaphene) was found within soils obtained from residences immediately bordering the site (Ref. 17, p. 5). Based on this information, and using table 6-16 within the HRS guidance, a value of 20 was assigned (Ref. 09, table 6-16).

Reference: 17, 9

Resources

Resource Use: NO

Resource Value: 0

Documentation for Resources:

Resources have not been identified within the area surrounding the site and within the 4-mile target distance limit (Ref. 10, 001).

PRESCORE 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 14 AIR PATHWAY TARGETS

Olin, Wallsiville Road - 07/24/95

Actual Contamination, Sensitive Environments

Sensitive Environment	Distance (miles)	Sensitive Environment Value	
- N/A and/or data not	specified		

Actual Contamination, Wetlands

Distance	Wetland	Wetland
Category	Acreage	Acreage Value
- N/A and/or data no	ot specified	

Sensitive Environments Actual Contamination Factor: 0 000

Sensitive Environments Actual Contamination Factor: 0.000 (Sum of Sensitive Environments + Wetlands Values)

PREscore 3.0 - PRESCORE.TCL File 07/25/94 PAGE: AIR PATHWAY TARGETS Olin, Wallsiville Road - 07/24/95

15

Potential Contamination, Sensitive Environments

Sensitive Environment	Distance (miles)	Sensitive Environment Value	Distance Weight	Weighted Value/10
	0.000	0	1.0000	0.000

Potential Contamination, Wetlands

Distance	Wetland	Wetland	Distance	Weighted
Category	Acreage	Acreage Value	Weight	Value/10

- N/A and/or data not specified

Sensitive Environment Potential Contamination Factor: 0.000

Documentation for Sensitive Environment :

No sensitive environments within 15-mile TDL (Ref. 18, 001).

1. Record of Communication to: Steve Hamm, TNRCC, Houston District Office From: Ken Jensen, Fluor Daniel, Inc., Regarding Current Agency (TNRCC) Activities at the S.P. Oliver Site, 5/18/95.

- 2. Record of Communication To: Bob Devillier, City of Houston Zoning and Planning Department From: Ken Jensen, Fluor Daniel, Inc., Regarding Zoning of the S.P. Oliver site 5/16/95.
- 3. U.S. Environmental Protection Agency, 1985. Potential Hazardous Waste Site Inspection Report. Author Bill Carrothers, 12/29/80.
- 4. Herschfield, David M., 1961, U.S. Department of Commerce U.S. Weather Bureau. Technical Paper Number 40 Rainfall Frequency Atlas of the United States
- 5. U.S. Environmental Protection Agency, Graphical Exposure Modeling System (GEMS) Database, compiled from the U.S. Census Bureau 1990 data accessed 3/27/95.
- 6. U.S. Environmental Protection Agency, 1985. Hazard Ranking System scoring document Attachment: "Documentation Records for Hazard Ranking System" 10/10/85.
- 7. Texas Water Development Board, Records of Wells, Springs and Test Holes for Harris County, 1995.
- 8. Harris-Galveston Coastal Subsidence District computer search of public and private wells within 4-mile radius of the S.P.Oliver site.
- 9. U.S. Environmental Protection Agency. Final Rule Hazard Ranking System, FR 51532-51667, December 14, 1990.
- 10. Record of Communication To: Tom Parker, Harris County Flood Control District, From: Ken Jensen, Fluor Daniel, Inc., Regarding Surface & GW Usage in Areas Adjacent & Downstream of S.P. Oliver site 6/2/95
- 11. Record of Communication To: Dave Terry, Texas Natural Resources Conservation Commission, From: Ken Jensen, Fluor Daniel, Inc., Regarding Wellhead Protection Areas in vicinity of S.P. Oliver site.
- 12. Record of Communication To: Johnnie Kennedy, Texas TNRCC, From: Ken Jensen, Fluor Daniel, Inc., Regarding: Analysis of Recent S.P. Oliver Site Samples, 5/17/95.

PAGE: 1

2

PREscore 3.0 - PRESCORE.TCL File 07/25/94 REFERENCES

Olin, Wallsiville Road - 07/24/95

- Ecology and Environment, Inc., February 10, 1982. Memorandum from 13. Imre Sekelyhidi, E&E To: Dave Peters, Chief, Hazardous Wastes section (included in EPA file).
- Roy F. Weston, Inc., 1985, Site Assessment Report on S.P. Oliver Pesticide Plant, Houston, Harris County, Texas. 10/21/85.
- 15. Harris-Galveston Coastal Subsidence District database printout of Registered Wells located within a 4-mile Radius of the Site. 5/19/95.
- Record of Communication to: Mark Leudke, Lance Robinson, TNRCC 16. Fisheries personnel From: Ken Jensen, Fluor Daniel, Inc., Re: Rec. & Comm. fishing within Hunting Bayou and Houston Ship Ch.
- 17. Stennie Meadours, TNRCC, 1990. Memo to Ernest Heyer, TNRCC. Subject: "Olin/Texas Water Commission Settlement Agreement; Sample Analysis Results", 5/17/90.
- 18. Record of Communication to: Shannon Breslin, Texas Natural Heritage Program From: Ken Jensen, Fluor Daniel, Inc., Re: Threatened or Endangered Species Within the TDL of S.P. Oliver Site 5/23/95.
- 19. U.S. Department of the Interior, Fish and Wildlife Service, Nation Wetlands Inventory maps: Settegast, TX, Jacinto City, TX, Park Place, TX, Pasadena, TX.
- 20. U.S. Geological Survey, 7.5 Minute Series Topographic Maps: Settegast (1982), Jacinto City (1982), Park Place (1982) and Pasadena (1983) Texas.
- 21. Texas Water Resources Data, Water Year 1991, Volume 2. San Jacinto River Basin, Brazos River Basin, San Bernard River Basin, and Intervening Coastal Basins. U.S. Geological Survey Report TX-91-2.
- 22. U.S. Department of Commerce County and City Data Book, 1994.
- Land Resources Laboratoru Map Series: Land and Water Resources-23. Houston-Galveston Area Council. Bureau of Economic Geology, 1975.
- U.S. Geological Survey, Water Resources Investigations Report 87-4153. 24. Ground-Water Withdrawals and Changes in Ground-Water Levels, Ground-Water Quality, etc. in the Houston District, Texas, 1980-84.
- 25. Geologic Atlas of Texas, Houston Sheet, 1:250,000. Bureau of Economic Geology, Austin, Texas, 1982.

PREscore 3.0 - PRESCORE.TCL File 07/25/94 PAGE: 3 REFERENCES

Olin, Wallsiville Road - 07/24/95

26. U.S. Environmental Protection Agency. Hazard Ranking System Guidance Manual. EPA540-R-92-026. November 1992.